View NSN Online: https://aerobasegroup.ae/nsn/3439-00-224-3580

HARRIS J W CO INC -- STAY-SILV 15 -- 3439-00-224-3580

Product ID:STAY-SILV 15 MSDS Date:04/01/1990 FSC:3439 NIIN:00-224-3580 MSDS Number: BDKKK === Responsible Party === Company Name: HARRIS J W CO INC Address:10930 DEERFIELD RD City:CINCINNATI State:OH ZIP:45242-4110 Country:US Info Phone Num:513-891-2000 Emergency Phone Num:513-891-2000 CAGE: JO820 === Contractor Identification === Company Name: J. W. HARRIS CO., INC Address:10930 DEERFIELD RD Box:City:CINCINNATI State:OH ZIP:45242-4110 Country:US Phone:513-891-2000 CAGE: JO820 Company Name: J. W. HARRIS CO., INC. Address:10930 DEERFIELD ROAD Box:City:CINCINNATI State:OH ZIP:45242-4110 Country:US Phone:513-891-2000 CAGE:27911

Ingred Name:SILVER (SARA III) CAS:7440-22-4 RTECS #:VW3500000 Fraction by Wt: 15% Other REC Limits:NONE SPECIFI ED OSHA PEL:0.01 MG/M3 ACGIH TLV:0.1 MG/M3; 9192 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:COPPER (SARA III) CAS:7440-50-8 RTECS #:GL5325000 Fraction by Wt: 80.0% Other REC Limits:NONE SPECIFIED OSHA PEL:0.1MG/M3 FUME/1 DUST ACGIH TLV:0.2MG/M3 FUME; 9192 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:PHOSPHOROUS (YELLOW) (SARA III) CAS:7723-14-0 RTECS #:TH3500000 Fraction by Wt: 5.0% Other REC Limits:NONE SPECIFIED OSHA PEL:0.1 MG/M3 ACGIH TLV:0.1 MG/M3; 9192 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:HAZARDS INCLUDE BREATHING OF METAL OXIDE FUMES, METAL FUME FEVER, ULTRAVIOLET LIGHT BURNS OF SKIN AND/OR EYES, THERMAL BURNS, AND ELECTRIC SHOCK.
Explanation of Carcinogenicity:THE PRODUCT CONTAINS NO INGREDIENT THAT IS LISTED BY IARC, NTP OR OSHA AS A CARCINOGE
N.
Effects of Overexposure:EXPOSURE TO WELDING FUMES MAY RESULT IN DIZZINESS, NAUSEA, METAL FUME FEVER AND/OR IRRITATION OF NOSE, THROAT AND EYES. TOXIC GASES CAN BE FATAL.
Medical Cond Aggravated by Exposure:SOME WORKERS MAY BE AFFECTED BY A PRE-EXISTING CONDITION OR OTHER OCCUPATIONAL ILLNESS BECAUSE OF THE WIDE VARIATION IN INDIVIDUAL SUSCEPTIBILITIES.

First Aid:FUME INHALATION:REMOVE FROM EXPOSURE. GET MED

ICAL ATTENTION. THERMAL BURN:USE NORMAL FIRST AID. ULTRAVIOLET EXPOSURE:SKIN;TREAT AS SUNBURN. EYE; GET MEDICAL ATTENTION. ELECTRIC SHOCK:TURN OFF POWER. R EMOVE AND RESTORE BREATHING IF NECESSARY. GET MEDICAL ATTENTION.

Flash Point:NON-FLAMMABLE Extinguishing Media: PRODUCT IS NON FLAMMABLE. EXTINGUISH FIRE WITH MEDIA APPROPRIATE FOR SOURCE OF FIRE. Fire Fighting Procedures: FIRE FIGHTERS SHOULD USE NIOSH **APPROVED SCBA &** FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE. Unusual Fire/Explosion Hazard: ARCS, SPARKS OR HOT METAL FROM A WELDING OPERATION MAY IGNITE NEARBY COMBUSTABLE MATERIAL. Spill Release Procedures: CLEAN UP ANY GRINDING DUST OR WASTE RESIDUES AND PLACE IN SUITABLE DOT APPROVED CONTAINERS. AVOID INHALATION AND SKIN EXPOSURE. Neutra lizing Agent:NOT RELEVANT Handling and Storage Precautions:NO SPECIAL HANDLING IS REQUIRED. STORE AS DIRECTED BY MFR. Other Precautions: SEE ANSI STANDARD Z49.1-1983. READ "SAFETY IN WELDING AND CUTTING" FROM AMERICAN WELDING ASSOCIATION, 550 N.W. JEUNE RD., MIAMI, FL 33135. Respiratory Protection: USE NIOSH/MSHA WELD FUME RESPIRATOR OR AIR SUP PLIED RESPIRATOR WHEN CUTTING, GRINDING OR WELDING IN A CONFINED SPACE OR WHERE LOCAL EXHAUST OR GENERAL VENTILATION DOES NOT KEEP EXPOSURE BELOW PEL/TLV. Ventilation: USE LOCAL VENTILATION WHEN CUTTING, GRINDING OR WELDING TO KEEP THE DUST, FUMES & GASES FROM THE WORKERS BREATHING ZONE. Protective Gloves:WELDERS LEATHER GLOVES Eye Protection: OSHA APPR.GOGGLES/FACE SH'LD W/ANSI LENS Other Protective Equipment: FLAME RETARDANT CLOTHING WHEN CUTTING, **GRINDING OR WELDING. DO NOT EXPOS**

E SKIN TO RADIATION WHEN HOT CUTTING OR WELDING. Work Hygienic Practices: USE GOOD INDUSTRIAL HYGIENE. WASH THOROUGHLY BEFORE EATING OR SMOKING. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. Supplemental Safety and Health WELDING AND HOT CUTTING FUMES & GASES CANNOT BE CLASSIFIED SIMPLY. THEIR COMPOSITION AND QUANTITY ARE DEPENDENT ON THE METAL BEING WELDED. THE PROCEDURES. PROCESSES AND THE TYPE OF WIRE OR ELECTRODES USED. OTHER INFLUENCING FACTORS ARE THEPRESENCE OF CO NTAMINANTS, CHLORINATED SOLVENTS MAY DECOMPOSE TO TOXIC GASES. HCC:N1 Decomp Temp: Decomp Text: UNKNOWNUNKN Appearance and Odor:SILVER METAL ROD Stability Indicator/Materials to Avoid:YES NONE

Stability Condition to Avoid:NONE

Hazardous Decomposition Products: BRAZING AND CUTTING OPERATION MAY INCLUDE OXIDES OF THE METALS, COMPLEX METALLICS, AND OZONE.

Waste Disposal Methods: DISPOSE I/A/W FEDERAL, STATE & LOCAL REGULATIONS

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and

assume responsibility for the suitability of this information to their particular situation.