

SENTRY PAINT & CHEMICAL COMPANY -- X-4609 TT-E-489 -- 8010-00-664-4761

=====
Product Identification
=====

Product ID:X-4609 TT-E-489

MSDS Date:01/01/1985

FSC:8010

NIIN:00-664-4761

MSDS Number: BFKPL

=== Responsible Party ===

Company Name:SENTRY PAINT & CHEMICAL COMPANY

Address:MILL AND LAWRENCE ST

City:DARBY

State:PA

ZIP:19023

Country:US

CAGE:GO855

=== Contractor Identification ===

Company Name:S

ENTRY PAINT & CHEM CO

Address:MILL AND LAWRENCE ST

Box:City:DARBY

State:PA

ZIP:19023

Country:US

CAGE:GO855

Company Name:SENTRY PAINT AND CHEMICAL CO

Address:MILL AND LAWRENCE ST

Box:City:DARBY

State:PA

ZIP:19023

Country:US

CAGE:34346

=====
Composition/Information on Ingredients
=====

Ingred Name:MINERAL SPIRITS

CAS:64475-85-0

RTECS #:PY8240000

Fraction by Wt: 40.9%

ACGIH TLV:200 PPM

Ingred Name:LEAD (SARA III)

CAS:7439-92-1

RTECS #:OF7525000

Fraction by Wt: 0.16%

OSHA PEL:0

.05 MG/M3;1910.1025
ACGIH TLV:0.15 MG/M3;DUST 9192
EPA Rpt Qty:1 LB
DOT Rpt Qty:1 LB

=====
===== Hazards Identification =====

Effects of Overexposure:SWALLOW-GI IRRITANT;IRRITATE EYES & SKIN.
INHALE: NASALT RESP IRRIT; DIZZINESS, WEAKNESS, NAUSEA,ETC

=====
===== First Aid Measures =====

First Aid:SKIN: WASH W SOAP & WATER; EYES-FLUSH W LGE AMTS WATER-GET
MED AID. INGEST-DO NOT INDUCE VOMITING-GET MED AID. INHALATION:
REM
OVE TO FRESH AIR; ADMIN OXYGEN OR ARTIFICIAL RESP IF NECESSARY.
GET MED AI D. REMOVE CONTAMINATED CLOTHING. LAUNDRER BEF REUSE

=====
===== Fire Fighting Measures =====

Extinguishing Media:FOAM, CO2, DRY CHEM
Fire Fighting Procedures:WATER NOT EFFECTIVE USE MESA/NIOSH BREATH
APPAR PRESS DEMAND
Unusual Fire/Explosion Hazard:VAPORS MAY SPREAD & IGNITE. DO NOT WELD
OR USE CUTTING TOECH EVEN ON EMPTY DRUMS.

=====
===== Accidental Release Measures ====
=====

Spill Release Procedures:ELIMINATE IGFNITION SOURCES. WEAR PROTECTIVE
EQUIP. DIKE MAT'L W INERT MAT'L & TRANSFER TO CONTAINERS FOR
DISPOSAL OR RECOVERY. KEEP SPILL OUT OF MUNICIPAL SEWERS OR OPEN
BODIES OF WATER.

=====
===== Handling and Storage =====

Handling and Storage Precautions:KEEP OUT OF SUN & AWAY FROM HEAT.
DRUMS SHOULD BE GROUNDED WHILE POURING. LIMIT FREE FALL TO A FEW
INCHES.
Other Precautions:KEEP CONTAINER CLOSED

WHEN NOT IN USE. DO NOT CUT,
PUNCTURE OR WELD ON OR NEAR CONTAINER.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:IF TLV EXCEEDED, NIOSH/MESA BREATHING APPARATUS.

Ventilation:SUFFICIENT TO MAINTAIN EXPOSURE BELOW TLV

Protective Gloves:BONP-N

Eye Protection:SPLASH GOGGLES

Other Protective Equipment:NORMAL WORK CLOTHING; EYE BATH & SAFETY
SHOWER AVAILABLE.

Supplemental Safety and Health

===== Physical/Chemical Properties =====

=====

HCC:F4

Vapor Density:>AIR

Evaporation Rate & Reference: