View NSN Online: https://aerobasegroup.ae/nsn/9160-00-926-2124

Product ID:UNIVOLT 60-1830 MSDS Date:01/01/1987 FSC:9160 NIIN:00-926-2124 MSDS Number: BFWTM === Responsible Party === Company Name: OCTAGON PROCESS, INC. Address:596 RIVER ROAD City:EDGEWATER State:NJ ZIP:07020 Country:US Info Phone Num:201-945-9400 Emergency Phone Num:201-945-9400 CAGE:DO973 === Contract or Identification === Company Name: OCTAGON PROCESS INC. Address:596 RIVER ROAD Box:City:EDGEWATER State:NJ ZIP:07020 Country:US Phone:201-945-9400 CAGE:82925 Company Name: OCTAGON PROCESS, INC. Address:596 RIVER ROAD City:EDGEWATER State:NJ ZIP:07020-1105 Country:US Phone:201-945-9400 CAGE:DO973

Ingred Name:COMPLEX MIXTURE OF PETROLEUM HYDROCARBONS.(PER MSDS,PRODUCT DOES NOT CONTAIN ANY PCB'S) Other REC Limits:5MG/CUM,AS OI Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Health Hazards Acute and Chronic:ACUTE:SKIN IRRITATION ON PROLONGED CONTACT;OIL MIST,MAY CAUSE RESPIRATORY IRRITATION OR EYES IRRITATION. CHRONIC:NOT KNOWN. Explanation of Carcinogenicity:NOT SPECIFIED Medical Cond Aggravated by Exposure:NO DATA IS AVAILABLE

First Aid:SKIN:WASH W.SOAP & H*20. EYES:FLUSH W. H*20. INGESTED:DON'T INDUCE VOMITING. INHALED:REMOVE TO FRESH AIR. GIVE CPR/OXYGEN IF NEED. KEEP WARM & QUIET. REMOVE CONTAMINATED CLOTHING. NEVER GIVE ANYTHING BY MOUTH TO UNCONSCIOUS PERSON.

Flash Point Method:COC Flash Point:320F/160C Lower Limits:1 Upper Limits:7 Extinguishing Media:CO*2, FOAM, DRY CHEM & H*20 FOG. Fire Fighting Procedures:WEAR SELF-CNTD BRTHG,APP H*20 SPRAY TO COOL

CONTR.

Unusual Fire/Explosion Hazard:DO NOT MIX WITH OR STORE NEAR STRONG OXIDIZERS.LIKE LIQUID CHLORINE OR CONCENTRATED OXYGEN.

Spill Release Procedures: ELIMINATE IGNITION SOURCES. STOP LEAK. EVACUATE AREA.DO NOT TOUCH SPILLAGE. SM SPILL: ABSORB W. INERT ABSORBENT. PLACE IN CLOSED CONTAINER. FLUSH AREA W. WATER. LG SPILL: DIKE AHEAD FOR LATER DISPOSAL. NOTIFY AUTHORITIES.

========================== Handling and S

Handling and Storage Precautions:STORE IN COOL,DRY,WELL VENT,LOW FIRE RISK AREA. PROTECT CONTRS FROM PHYS DAMAGE.KEEP OUT OF DIR RAYS OF SUN AWAY FR ORG PROD & OTHER EASILY OXID MATL
Other Precautions:AVOID BREATHING OIL MIST.REMOVE CONTAMINATED CLOTHING,LAUNDER BEFORE RE-USE.DISCARD OIL SOAKED SHOES.WASH WITH SOAP & WATER AFTER HANDLING.

====== Exposure Controls/Personal Protection ==========

Respiratory Protection:SCBA IN ENCLOSED AREAS. Ventilation:LOCAL EXHAUST TO ELIMINATE MISTS/FUMES/GASES. Protective Gloves:IMPERVIOUS Eye Protection:GOGGLES/FACE SHIELD Other Protective Equipment:EYE WASH STATION. APRONS. SPECIAL IMPERVIOUS CLOTHING. Supplemental Safety and Health

HCC:N1 Boiling Pt:B.P. Text:550F/288C Vapor Pres: