

AMERON INC. -- AMERCOAT,78 RESIN RED -- 8010-00-997-2611

=====
Product Identification
=====

Product ID:AMERCOAT,78 RESIN RED

MSDS Date:01/01/1987

FSC:8010

NIIN:00-997-2611

Kit Part:Y

MSDS Number: BGCKV

=== Responsible Party ===

Company Name:AMERON INC.

Address:201 N BERRY ST

City:BREA

State:CA

ZIP:92621-3904

Country:US

CAGE:JO831

=== Contractor Identification ===

Company Name:AMERON INC.

Address:

201 N BERRY ST

Box:City:BREA

State:CA

ZIP:92621-3904

Country:US

CAGE:JO831

Company Name:AMERON INTERNATIONAL PROTECTIVE COATINGS GROUP

Address:201 NORTH BERRY ST.

Box:City:BREA

State:CA

ZIP:92821

Country:US

Phone:714-529-1951

CAGE:55849

=====
Composition/Information on Ingredients
=====

Ingred Name:COAL TAR CAS# 8007-45-2

CAS:8007-45-2

RTECS #:GF8600000

Fraction by Wt: 23%

ACGIH TLV:0.2 MG/CUM

Ingred Name:EPOXY RESIN CAS# 65068-38-6

Fraction by Wt: 18%

ACGIH TLV:2 PPM(SKIN

)

Ingred Name:NAPHTHALENE (SARA III)
CAS:91-20-3
RTECS #:QJ0525000
Fraction by Wt: 12%
OSHA PEL:10 PPM/15 STEL
ACGIH TLV:10 PPM/15 STEL; 9192
EPA Rpt Qty:100 LBS
DOT Rpt Qty:100 LBS

Ingred Name:METHYL N-AMYL KETONE
CAS:110-43-0
RTECS #:MJ5075000
Fraction by Wt: 4%
OSHA PEL:100 PPM
ACGIH TLV:50 PPM; 9192

Ingred Name:XYLENES (O-,M-,P- ISOMERS) (SARA III)
CAS:1330-20-7
RTECS #:ZE2100000
Fraction by Wt: 2%
OSHA PEL:100 PPM/150 STEL
ACGIH TLV:100 PPM/150STEL;9192
EPA Rpt Qty:1000 LBS
DOT Rpt Qty:
1000 LBS

=====
===== Hazards Identification =====

Effects of Overexposure:IRRIT:SKIN,MUC MEMB,EYE,RESP
SYS.INHAL:HDCH,NAUS,DIZ,ASPHYXIA.SKIN SENSITIZATION.OTH PRECAUTION.

=====
===== First Aid Measures =====

First Aid:INHAL:FRESH AIR.GIVE O*2,CPR.SKIN:WASH THOROUGHLY WITH SOAP
AND WATER.EYE:FLUSH IMMEDIATELY WITH PLENTY OF WATER FOR 15 MIN AND
GET MEDICAL ATTENTION.LAUNDER CONTAMINATED CLOTHING BEFORE
REUSE.INGEST: D
O NOT INDUCE VOMITING;CALL PHYSICIAN IMMEDIATELY.

=====
===== Fire Fighting Measures =====

Flash Point:107F,42C SCC
Lower Limits:1.1
Extinguishing Media:FOAM,CO*2,DRY CHEMICAL
Unusual Fire/Explosion Hazard:ISOLATE FROM HEAT,ELECTRICAL
EQUIPMENT,SPARKS AND OPEN FLAME.WEAR SELF-CONTAINED BREATHING
APPARATUS

=====
===== Accidental Release Measures =====

Spill Release Procedures:ELIMINATE ALL SOURCES OF IGNITION.USE
ABSORBENT CLEANUP

