View NSN Online: https://aerobasegroup.com/nsn/8040-01-016-0554

Product ID:SCOTCHWELD 2216A ADHESIVE (TRANSLUCENT) MSDS Date:01/01/1987 FSC:8040 NIIN:01-016-0554 Kit Part:Y **MSDS Number: BGDPK** === Responsible Party === Company Name: 3M COMPANY-ADHESIVES, COATINGS & SEALERS DIV Emergency Phone Num:612-733-1110 (OP55) CAGE:0 4963 === Contractor Identification === Company Name: 3M MINNESOTA MINING AND MFG CO ADHESIVES SEALERS DIV Address:3M CTR Box:City:SAINT PAUL State:MN ZIP:55144-1000 Country:US Phone:800-364-3577/651-737-6501(24 HOURS) CAGE:04963 Ingred Name: ALIPHATIC AMINE

Fraction by Wt: 61.0% ACGIH TLV:N/D

Effects of Overexposure: EYE: EXTR IRRT MAY CAUSE PERM EYE DAMAGE.

SKN:IRRT & SENS. INHL:IRRT.INGES:IRRT GI TRACT.

First Aid:EYE: FLUSH COPIOUSLY WATER 10 MIN. SKIN:THOROUGH WASH SOAP & WATER. INH: REMOVE TO FRESH AIR. INGES: DRINK TWO GLASSES MILK OR WATER. CALL PHYSICIAN. INDUCE VOMITING.

Flash Point:>200F CC Extinguishing Media:CO2,FOAM,DRY CHEMICAL, WATER Fire Fighting Procedures:WEAR SELF-CNTND BRTHG APP U nusual Fire/Explosion Hazard:NONE Spill Release Procedures: VENTILATE AREA, COLLECT SPILLED MATERIAL. CLEANUP RESIDUE, PLACE IN APPROVED METAL CONTAINER. Handling and Storage Precautions: AVOID CONTACT WITH EYE & SKIN. AVOID INHL OR EYE CONTACT WITH DUST FROM GRINDING OPERATIONS. WASH CONTAMINATED CLOTHING BEFORE REUSE. Other Precautions: VENT CURIN G OVENS TO OUTDOORS. KEEP CONTAINERS CLOSED. **Respiratory Protection:NONE** Ventilation: MECH (GEN) OR LOCAL EXHAUST THAT PROVIDES ADEQUATE VENTILATION Protective Gloves: IMPERVIOUS Eye Protection:SAFETY GLASSES Other Protective Equipment: SCBA IN FIRE. USE DUST MASK WHEN GRINDING CURED RESIN. Supplemental Safety and Health PART A OF TWO PART KIT. BASIS: MSDS DTD 1 NOV 85 (OSHA HAZCOMSTD), 3M DOCUMENT 1031731. 3M GENER IC P/N IS 62-3608-XXXX-X, KIT ALSO KNOWN AS 2216B/A OR 3M EC-2216B/A (TRANSLUCENT).KEY1:N1. 

HCC:N1 Spec Gravity:0.97 Viscosity:7000 CP Solubility in Water:INSOLUBLE Appearance and Odor:AMBER PASTE Percent Volatiles by Volume:0

Stability Indicator/Materials to Avoid:YES Hazardous Decomposition Products:CO, CO2, N, SMOKE PARTICLES ON EXPOSURE EXCESS H

## EAT OR FLAME

Waste Disposal Methods:OBSERVE ALL APPLICABLE REGS BEFORE DISPOSAL. CURED RESIN (A&C):DISPOSE IN SAN LANDFILL. SPILL: DISPOSE OF CLEANUP MATERIAL BY INCINERATION.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants thi s information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.