

CIBA-GEIGY CORP. -- ARALDITE 508 -- 8040-01-036-8963

=====
Product Identification
=====

Product ID:ARALDITE 508

MSDS Date:01/01/1987

FSC:8040

NIIN:01-036-8963

MSDS Number: BGGSQ

=== Responsible Party ===

Company Name:CIBA-GEIGY CORP.

Emergency Phone Num:914-478-3131

CAGE:EO102

=== Contractor Identification ===

Company Name:CIBA-GEIGY CORP ADDITIVES DIV.

Address:SEVEN SKYLINE DRIVE

Box:City:HAWTHO

RNE

State:NY

ZIP:10532-2119

Country:US

Phone:800-888-8372

CAGE:07566

Company Name:CIBA-GEIGY CORP. PLASTICS & ADDITIVES DIV

Address:THREE SKYLINE DRIVE

Box:18300

City:HAWTHORNE

ZIP:10532

Country:US

CAGE:EO102

=====
Composition/Information on Ingredients
=====

Ingred Name:EPOXY RESIN

=====
Hazards Identification
=====

Effects of Overexposure:ACUTE ORAL TOXICITY= LD 50=> 4.5 GR/KG

=====
First Aid Measures
=====

=====

First Aid:WASH SKIN AT FIRST OPPORTUNITY W/SOAP & WATER.

===== Fire Fighting Measures =====

Flash Point:430F COC 221C

Extinguishing Media:CLASS B CO*2, DRY CHEMICAL FOAM

Fire Fighting Procedures:NONE

Unusual Fire/Explosion Hazard:NONE

===== Accidental Release Measures =====

Spill Release Procedures:BRUSH OR WORK INTO THE SPILLED RESIN PENETONE
SRN OR BUTYL CARBITOL & FLUSH W/WATER. FOR SMALL SPILLS ACETONE CAN
BE
USED.

===== Handling and Storage =====

Handling and Storage Precautions:STORE IN SEALED CONTAINERS. KEEP
CONTAINERS CLOSED TO PREVENT MOISTURE ABSORPTION. AVOID SKIN & EYE
CONTACT, WASH IMMED. AFT CONTCT W/SOAP & WATER.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:NOT NECESSARY

Ventilation:SEE TSN 89.

Protective Gloves:RECOM,NOT REQD

Eye Protection:SAFETY GLASSES

Supplemental Safety and Health

PROCURED U

NDER ARALDITE 508; KEY1:N1.

===== Physical/Chemical Properties =====

HCC:N1

Spec Gravity:9.4

Evaporation Rate & Reference: