View NSN Online: https://aerobasegroup.com/nsn/8040-00-180-5941

Product ID:SCOTCHWELD 18388 ADHESIVE (GREEN) MSDS Date:01/01/1987 FSC:8040 NIIN:00-180-5941 Kit Part:Y MSDS Number: BGSWC === Responsible Party === Company Name: 3M COMPANY - ADHESIVES, SEALERS & COATINGS DIV Emergency Phone Num:612-733-1110 OP55 CAGE:04963 ____ Contractor Identification === Company Name: 3M MINNESOTA MINING AND MFG CO ADHESIVES SEALERS DIV Address:3M CTR Box:City:SAINT PAUL State:MN ZIP:55144-1000 Country:US Phone:800-364-3577/651-737-6501(24 HOURS) CAGE:04963 Ingred Name: POLYAMIDE RESIN Fraction by Wt: 81.0% Ingred Name: PIGMENTS & FILLERS Fraction by Wt: 19.0% Effects of Overexposure:EYE:SEVERE IRRT DIRECT CONTACT.SKN:MOD IRRT POSS SENSITIZATION.INH:NO SOLVENT VAP.INGES:LOW TOX First Aid:EYE:FLUSH 10 MIN W/WATER,CALL PHYS.SKN:WASH THOROUGHLY SOAP & WATER. INHL: PROVIDE FRESH AIR. INGEST: NO ACTION NEEDED. Extinguishing Media:CO*2, FOAM, DRY CHEMICALS Fire Fighting Procedures: USE SCBA WHEN FIGHTING FIRES INVOLVING THIS MATERIAL. Unusual

Fire/Explosion Hazard:NONE Spill Release Procedures: OBSERVE ALL PRECAUTIONS. VENTILATE CONFINED AREAS. COLLECT SPILLAGE & PLACE IN APPROVED CONTAINER. Handling and Storage Precautions: USE ONLY IN WELL VENTILATED AREAS. AVOID INHL DUST. AVOID CONTACT WITH EYES & SKIN. WASH CONTAMINATED CLOTHING BEFORE REUSE. Other Precautions: LAUNDER CONTAM CLOTHIN G BEFORE REUSE Respiratory Protection: USE DUST MASK WHEN SAWING OR GRINDING CURED RESIN. Ventilation: VENT CURING OVENS TO OUTDOORS. PROVIDE LOC EXH IN CONF AREAS Protective Gloves: USE IMPERVIOUS Eye Protection: USE SAFETY GLASSES Other Protective Equipment:NONE Supplemental Safety and Health PART A OF TWO PART SCOTCHWELD 1838B/A EPOXY ADHESIVE (GREEN) KIT.UPDATE PER 3M MSDS 1NOV85 (OSHA) DOC# 1031400. 3M GENERIC ID# IS 62-1839-XXXX-X.FORMER P/N:SCOTCHWELD EC1838A. Spec Gravity:0.95 Viscosity:PASTE Solubility in Water:NIL

Appearance and Odor:GREEN VISCOUS PASTE WITH LITTLE ODOR Percent Volatiles by Volume:0

Stability Indicator/Materials to Avoid:YES Stability Condition to Avoid:NONE Hazardous Decomposition Products:POSS CO,CO*2, N DECOMP PRODUCTS WHEN EXP EXCESS HEA

T,FLAME

Waste Disposal Methods:CURED RESIN: DISPOSE IN APPROVED LANDFILL OR INCINERATE PER REGS. UNCURED WASTES: INCINERATE IN APPROVED DISPOSAL FACILITY.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be a ccurate and

disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.