View NSN Online: https://aerobasegroup.com/nsn/8010-01-344-5317

## DAVLIN PAINT CO INC -- MIL-E-24635A 26307 -- 8010-01-344-5317

Product ID:MIL-E-24635A 26307

MSDS Date:03/20/1992

FSC:8010

NIIN:01-344-5317

MSDS Number: BPMXR === Responsible Party ===

Company Name: DAVLIN PAINT CO INC

Address:700 ALLSTON WAY

Box:2308

City:BERKELEY

State:CA ZIP:94702 Country:US

Info Phone Num:510-848-2863

Emergency Phone Num:510-848-2863

Preparer'

s Name:PATRICIA SHAW

CAGE:3Z268

=== Contractor Identification ===

Company Name: DAVLIN PAINT CO INC

Address:700 ALLSTON WAY

Box:2308

City:BERKELEY

State:CA ZIP:94702 Country:US

Phone:510-848-2863

CAGE:3Z268

======= Composition/Information on Ingredients ========

Ingred Name: N-BUTYL ACETATE (VAPOR PRESSURE 8.7 MM HG @ 68F)

CAS:123-86-4

RTECS #:AF7350000 Fraction by Wt: 2%

Other REC Limits: NONE SPECIFIED

OSHA PEL:150 PPM ACGIH TLV:150 PPM EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

In

gred Name: METHYL N-AMYL KETONE (VAPOR PRESSURE 2.6 MM HG @ 68F) CAS:110-43-0 RTECS #:MJ5075000 Fraction by Wt: 20% Other REC Limits: NONE SPECIFIED **OSHA PEL:100 PPM ACGIH TLV:50 PPM** Ingred Name:MICA CAS:12001-26-2 RTECS #:VV8760000 Fraction by Wt: 2% Other REC Limits: NONE SPECIFIED **OSHA PEL:20 MPPCF** ACGIH TLV:3 MG/M3 RDUST: 9293 Ingred Name:TALC CAS:14807-96-6 RTECS #:MW2700000 Fraction by Wt: 15% Other REC Limits: NONE SPECIFIED ACGIH TLV:2 MG/M3 RDUST ====== Hazards Identifica tion ========= Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic: STUDIES SHOW THAT MANY PETROLEUM HYDROCARBONS/SYNTHETIC LUBRICANTS POSE POTENTIAL HUMAN HEALTH RISKS WHICH MAY VARY FROM PERSON-PERSON. PRECAUTION: EXPOS TO LIQ/VAPORS/MISTS/FUMES SHOULD BE MINIMIZED. CHRONIC EXPOS MAY CAUSE DAMAGE TO CENTRAL NERV SYS/RESP SYS/LUNGS/EYES/SKIN/GASTROINTESTINAL TRACT/LIVER/S PLEEN/KIDNEYS

Effects of Overexposure: INHAL: EXCESS INHAL OF VAPOR-NASAL/RESP IRRIT/DIZZINESS/WEAKNESS/FATIGUE/NAUSEA/HEADACHE. HIGH CONC: CNTRL NERV SYS DEPRESS. EYE: SEVERE IRRIT/TEARING/REDNESS/BLURRED VISION. SKIN: MOD IRRIT/DEFATTING /DERMATITIS. INGEST: IRRIT OF DIGEST TRACT/CNTRL NERV SYS DEPRESS. ASPIR HAZARD. LUNG INFLAMM FROM SWALLOWING/VOMITING.

Medical Cond Aggravated by Exposure: RESPIRATORY TRACT IRRITATION, DERMATITIS, NAUSEA.

======= First

۸: ۵	1100011800	=======================================
$\neg$	MEGGINES	

First Aid:EYE: FLUSH W/WTR 15 MIN, LIFT LIDS. GET MED ATTN. SKIN: RMV CONTAM CLOTH, WASH THOROUGHLY W/SOAP & WTR. IF IRRIT PERSISTS, SEE DR. INHAL: RMV VICTIM TO FRESH AIR. APPLY ARTIF RESP OR ADMIN OXYGEN IF N EEDED. CONSULT A DR. INGEST: GIVE WTR OR MILK TO DRINK & PHONE FOR MED ADVICE. DO NOT MAKE PERSON VOMIT UNLESS DIRECTED BY MED PERSONNEL. IF MED ADVICE CANNOT BE OBTAINED, TAKE TO NEAREST EMERG HOSP

Flash Point Method:SCC

Flash Point:102F Lower Limits:1.1% Upper Limits:7.9%

Extinguishing Media:FOAM, ALCOHOL FOAM, CO2, DRY CHEMICAL, WATER FOG Fire Fighting Procedures:USE EXTINGUISHERS FOR NFPA FLAMM LIQ FIRE.
WATER MAY BE INEFFECT-MAY USE AS FOG TO COOL. ALL EXPOS TO PROD OF COMBUST SHOULD WEAR FULL PROTECT CLOTH/BREATH APP.

Unusual Fire/Explosion Hazard: VAPORS FORM EXPLOSIVE MIXTURE W/AIR BTWN LOWER/UPPER EXPLOSIVE LIMITS-CAN BE IGNIT

ED BY MANY SOURCES. CLSD

CNTNR MAY EXPLODE W/EXTREME HEAT. ISOLATE FROM HEAT,\*

======== Accidental Release Measures ===========

Spill Release Procedures:EVACUATE ALL NON-ESSENTIAL PERSONNEL. REMOVE ALL IGNITION SOURCES. VENTILATE THE AREA. PROVIDE APPROPRIATE PEOTECTIVE EQUIPMENT. DIKE AROUND THE SPILL AREA. COVER SPILL WITH INERT ABSORBANT AND TRANSF ER USING NON-SPARKING TOOLS.

============= Handling and Storage ==========================

## Handling a

nd Storage Precautions:STORE BELOW 80F IN A CLOSED CONTAINER. STORE IN ORIGINAL CONTAINER. AVOID FLAME AND HIGH TEMPERATURES. DO NOT STORE NEAR OXIDIZING AGENTS OR ACIDS.

Other Precautions:DO NOT TAKE INTERNALLY, AVOID PROLONGED OR REPEATED INHALATION OF HEATED VAPORS OR SPRAY MIST. KEEP AWAY FROM HEAT. GROUND ALL CONNECTIONS, CONTAINERS, ETC. WHEN POURING OR TRANSFERING TO MINIMIZE STA TIC ELECTRICITY. USE NON-SPARKING TOOLS.

====== Exposure Controls/Personal Pr

-44:	
OTDCTION .	=========
いいたいいいい	

Respiratory Protection:USE NIOSH/MSHA APPROVED EQUIP WHEN AIRBORN EXPOSURE LIMITS ARE EXCEEDED. CONSULT RESP MFR TO DETERMINE APPROP EQUIP FOR GIVEN APPLICATION. HIGH AIRBORN CONC MAY REQUIRE THE USE OF A SUPPLIED-AIR RESP OR SELF-CONTAINED BREATHING APPARATUS Ventilation:PROVIDE SUFFIC VENT TO CONTROL EXPOSURE LEVELS BELOW AIRBORN EXPOSURE LIMITS. VENT EQUIP MUST BE EXPLOSION PROOF Protective Gloves:CONSULT GLOVE MFR-DETERMINE APPROP TYPE Eye Protection

:CHEMICAL SAFETY GLASSES OR GOGGLES

Other Protective Equipment:WEAR IMPERM APRONS/PROTECT CLOTH WHEN POSSIBLE-PREVENT REPEAT/EXTEND EXPOS OF SKIN. USE OF HEAD CAPS IS STRONGLY RECOMM

Work Hygienic Practices: AFTER USING, WASH BEFORE EATING, TOILETING OR SMOKING.

Supplemental Safety and Health

======== Physical/Chemical Properties ===========

HCC:F4
Boiling Pt:B.P. Text:274-315F
Vapor Density:> THAN AIR
Spec Gravity:(H2O=1) 1.4
Viscosity: