

WESTERN INDUSTRIES INC/GERETT M A DIV -- LIQUEFIED PETROLEUM GAS OR PROPANE --
6830-00-261-7445

===== Product Identification =====

Product ID:LIQUEFIED PETROLEUM GAS OR PROPANE

MSDS Date:06/19/1990

FSC:6830

NIIN:00-261-7445

MSDS Number: BRCBB

=== Responsible Party ===

Company Name:WESTERN INDUSTRIES INC/GERETT M A DIV

Address:W156 N9073 PILGRIM RD

City:MENOMONEE FALLS

State:WI

ZIP:53052-0070

Coun

try:US

Info Phone Num:414-251-7860

Emergency Phone Num:414-251-7860

CAGE:0B3V2

=== Contractor Identification ===

Company Name:WESTERN INDUSTRIES INC/GERETT M A DIV

Address:W156 N9073 PILGRIM RD

Box:City:MENOMONEE FALLS

State:WI

ZIP:53052-0070

Country:US

Phone:414-251-7860

CAGE:0B3V2

===== Composition/Information on Ingredients =====

Ingred Name:PROPANE

CAS:74-98-6

RTECS #:TX2275000

Fraction by Wt: 2.2-9.6%

Other REC Limits:1800 MG/CUM

OSHA PEL:1000 PPM

ACGIH TLV:SIMPLE ASPHYX

IANT

Ingred Name:AIR

Ingred Name:ODORANT

=====
===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:INHALATION: DIZZINESS TO ANESTHESIA &
RESPIRATORY ARREST. EYES: IRRITATION. SKIN: FREEZING OF TISSUE
CAUSING INJURY SIMILAR TO THERMAL BURN.
Explanation of Carcinogenicity:NONE

=====
===== First Aid Measures =====
=====

First Aid:INHALATION: REMOVE TO FRESH AIR. GUARD AGAINST SELF-INJURY.
APPLY ARTIFICIAL RESPIRATION IF BREATHING HAS STOPPED. OBTAIN
MEDICAL ATTENTION IN ALL CASES.

=====
===== Fire Fighting Measures =====

Lower Limits:2.15%
Upper Limits:9.60%
Extinguishing Media:WATER SPRAY: CLASS A-B-C OR BC FIRE EXTINGUISHERS.
Fire Fighting Procedures:STOP FLOW OF GAS. USE WATER TO KEEP FIRE
EXPOSED CONTAINERS COOL. USE WATER SPRAY TO DISPERSE UNIGNITED GAS
OR VAPOR.
Unusual Fire/Explosion Hazard:IF IGNITION OCCURRED & NO WATER
AVAILABLE, OVERHEATING MAY WEAKEN TANK. EVACUATE AREA. IF GAS
HASN'T IGNITED, GAS/VAPOR MAY BE DISPERSED BY WATER SPRAY/FLOODING

=====
===== Accidental Release Measures =====

Spill Release Procedures:EVACUATE AREA. SHUT OFF SUPPLY OF GAS.
ELIMINATE IGNITION SOURCES. VENTILATE AREA. DISPERSE W/WATER SPRAY.

=====
===== Handling and Storage =====

Handling an

d Storage Precautions:STORE AT TEMPERATURES 120F, HEAT, DIRECT SUNLIGHT
OR OTHER IGNITION SOURCES.

===== Disposal Considerations =====

Waste Disposal Methods:EMPTY CYLINDERS. DISPOSE OF IN LANDFILL IN
ACCORDANCE W/FEDERAL, STATE & LOCAL REGULATIONS. FLAMMABLE, CLASS
2. UN 1075.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States
of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.