

JET-LUBE INC -- WLD

=====

MSDS Safety Information

=====

FSC: 9150
NIIN: 01-179-0228
MSDS Date: 08/11/1993
MSDS Num: BVVCX
Product ID: WLD
MFN: 01
Responsible Party
Cage: 07431
Name: JET-LUBE INC
Address: 4849 HOMESTEAD RD
Box: 21258
City: HOUSTON TX 77226
Info Phone Number:
713-674-7617
Emergency Phone Number: 713-674-7617/800-424-9300(CHEMTREC)
Preparer's Name: DONALD A. OLDIGES
Proprietary Ind: Y
Review Ind: Y
Published: Y

=====

Contractor Summary

=====

Cage: 07431
Name: JET-LUBE INC
Address: 4849 HOMESTEAD RD
Box: 21258
City: HOUSTON TX 77026
Phone: 713-674-7617

=====

Item Description Information

=====

=====

Item Manager: S9G
Item Name: GREASE,WIRE ROPE-EXPOSED GEAR
Specification Number: NONE
Type/Grade/Class: NONE
Unit of Issue: CN
Quantitative Expression: 00000000035LB
UI Container Qty: 0
Type of Container: CAN

=====

Ingredients

=====

Name: *** PROPRIETARY ***

=====

Health Hazard

s Data

=====

LD50 LC50 Mixture: TLV FOR OIL MIST IS 5 MG/M3.

Route Of Entry Inds - Inhalation: NO

Skin: NO

Ingestion: NO

Carcinogenicity Inds - NTP: NO

IARC: NO

OSHA: NO

Effects of Exposure: TARGET ORGANS:EYES, SKIN, RESPIRATORY TRACT. ACUTE-
PROLONGED EYE/SKIN CONTACT WILL CAUSE IRRITATION. PROLONGED INHALATION OF
VAPORS/OIL MIST WILL CAUSE LUNG IRRITATION & MAY BE HARMFUL. MAY BE
HARMFUL/FATAL IF INGESTED. CHRONIC- UNKNOWN.

Explanat

ion Of Carcinogenicity: NONE

Signs And Symptoms Of Overexposure: EYES, SKIN, RESPIRATORY TRACT IRRITATION

Medical Cond Aggravated By Exposure: HEART PROBLEMS IN HIGH VAPOR CONCENTRATION

First Aid: GET MEDICAL ATTENTION IF SYMPTOMS PERSIST. SKIN:REMOVE BY
WIPING/WATERLESS HAND CLEANER FOLLOWED BY WASHING SKIN WITH SOAP & WATER.
EYE:FLUSH WITH WATER FOR 15 MINUTES, HOLDING EYELIDS OPEN. INHALED:REMOVE TO
FRESH AIR & PROVIDE OXYGEN/CPR IF NEEDED. ORAL:DO NOT INDUCE VOMITING.
CALL PHYSICIAN.

=====

Handling and Disposal

=====

Spill Release Procedures: SCOOP UP EXCESS GREASE, WIPE UP WITH RAGS, PICK-UP
RESIDUE WITH NON-FLAMMABLE ABSORBENT MATERIAL SUCH AS DIATOMACEOUS EARTH,
SAND OR VERMICULITE. SWEEP UP AND TRANSFER TO A CONTAINER FOR PROPER DISPOSAL.
CLEAN AREA WITH APPROPRIATE CLEANER.

Neutralizing Agent: NOT RELEVANT

Waste Disposal Methods: CONSULT LOCAL, STATE AND
FEDERAL REGULATIONS FOR

PETROLEUM PRODUCTS AND CHLORINATED SOLVENTS DISPOSAL.

Handling And Storage Precautions: STORE AWAY FROM HEAT, STRONG OXIDIZING AGENTS
AND DIRECT SUNLIGHT.

Other Precautions: USE ONLY IN WELL VENTILATED AREAS. AVOID PROLONGED/REPEATED
BREATHING OF FUMES/MISTS. AVOID CONTACT WITH EYES AND SKIN. DO NOT TAKE
INTERNALLY. WASH THOROUGHLY AFTER USING. KEEP OUT OF REACH OF CHILDREN.

=====

Fire and Explosion Hazard Informa

tion
=====

Flash Point Method: COC
Flash Point Text: >430F,>221C
Autoignition Temp Text: 500F
Lower Limits: >0.9
Upper Limits: >7.0
Extinguishing Media: USE CARBON DIOXIDE, FOAM, SAND/EARTH OR DRY CHEMICAL.
WATER MAY CAUSE FROTHING.
Fire Fighting Procedures: WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A FULL
FACED SELF CONTAINED BREATHING APPARATUS. COOL FIRE EXPOSED CONTAINERS WITH
WATER SPRAY.
Unusual Fire/Explosion Hazard: N
ONE

=====

Control Measures

=====

Respiratory Protection: USE ONLY IN WELL VENTILATED AREA. IF EXCESSIVE MISTING
PRESENT, USE NIOSH-APPROVED SELF-CONTAINED BREATHING APPARATUS.
Ventilation: LOCAL EXHAUST
Protective Gloves: POLY VINYL ALCOHOL
Eye Protection: SAFETY GLASSES
Other Protective Equipment: EYE WASH STATION & SAFETY SHOWER
Work Hygienic Practices: OBSERVE GOOD PERSONAL HYGIENE PRACTICES
AND
RECOMMENDED PROCEDURES. WASH HANDS BEFORE EATING.

=====

Physical/Chemical Properties

=====

HCC: T6
NRC/State LIC No: NOT RELEVANT
B.P. Text: >165F,>74C
M.P/F.P Text: UNKNOWN
Decomp Text: UNKNOWN
Vapor Pres: <100
Vapor Density: >1
Spec Gravity: 1.10
Viscosity: UNKNOWN
Solubility in Water: NIL
Appearance and Odor: BLACK SEMI-FLUID WITH CHARACTERISTIC SOLVENT ODOR
Percent Volatile

s by Volume: 15 MAX
Corrosion Rate: UNKNOWN

Reactivity Data

Stability Indicator: YES
Stability Condition To Avoid: EXCESSIVE HEAT, FLAMES
Materials To Avoid: STRONG OXIDIZING AGENTS
Hazardous Decomposition Products: CARBON MONOXIDE, CARBON DIOXIDE, HYDROCHLORIC ACID, CARBONYL CHLORIDE, SULFUR DIOXIDE, OXIDES OF NITROGEN & OTHER GASES
Hazardous Polymerization Indicator: NO
Conditions
To Avoid Polymerization: NOT RELEVANT

Toxicological Information

Ecological Information

MSDS Transport Information

Regulatory Information

Other Information

Transportation Information

Responsible Party Cage: 07431
Trans ID NO: 113214
Product ID: WLD
MSDS Prepared Date: 08/11/1993
Review Date: 11/30/1994
MFN: 1
Net Unit Weight: 35.0 LBS
Multiple KIT Number: 0
Review IND: Y
Unit Of Issue: CN
Container QTY: 0
Type Of Container: CAN

Detail DOT Information

DOT PSN Code: ZZZ
DOT Proper Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION

Detail IMO Information

IMO PSN Code: ZZZ
IMO Proper

Shipping Name: NOT REGULATED FOR THIS MODE OF TRANSPORTATION

Detail IATA Information

IATA PSN Code: ZZZ

IATA Proper Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION

Detail AFI Information

AFI PSN Code: ZZZ

AFI Proper Shipping Name: NOT REGULATED BY THIS MODE OF T
RANSPORTATION

HAZCOM Label

Product ID: WLD

Cage: 07431

Company Name: JET-LUBE INC

Street: 4849 HOMESTEAD RD

PO Box: 21258

City: HOUSTON TX

Zipcode: 77026

Health Emergency Phone: 713-674-7617/800-424-9300(CHEMTREC)

Label Required IND: Y

Date Of Label Review: 11/30/1994

Status Code: C

MFG Label NO: UNKNOWN

Label Date: 11/30/1994

Origination Code: F

Eye Protection IND: YES

Skin Protectio

n IND: YES

Signal Word: WARNING

Health Hazard: Moderate

Contact Hazard: Moderate

Fire Hazard: None

Reactivity Hazard: None

Hazard And Precautions: TARGET ORGANS:EYES, SKIN, RESPIRATORY TRACT. ACUTE-
PROLONGED EYE/SKIN CONTACT WILL CAUSE IRRITATION. PROLONGED INHALATION OF
VAPORS/OIL MIST WILL CAUSE LUNG IRRITATION & MAY BE HARMFUL. MAY BE
HARMFU L/FATAL IF INGESTED. CHRONIC- UNKNOWN. STORE AWAY FROM OXIDIZERS &
SUNLIGHT. PICK-UP SPILL WITH DIATOMACEOUS EARTH. CLEAN AREA WITH CLEA

NER.

FIRST AID- GET MEDICAL ATTENTION IF SYMPTOMS PERSIST. SKIN: REMOVE BY WIPING/WATERLESS HAND CLEANER FOLLOWED BY WASHING SKIN WITH SOAP & WATER. EYE:FLUSH WITH WATER FOR 15 MINUTES, HOLDING EYELIDS OPEN. INHALED:REMOVE TO FRESH AIR & PROVIDE OXYGEN/CPR IF NEEDED. ORAL:DO NOT INDUCE VOMITING. CALL PHYSICIAN.

=====

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense.

The United States of America in no manner whatsoever expressly or implied warrants, states, or intends said information to have any application, use or viability by or to any person or persons outside the Department of Defense nor any person or persons contracting with any instrumentality of the United States of America and disclaims all liability for such use. Any person utilizing this instruction who is not a military or civilian employee of the

United States of America should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation regardless of similarity to a corresponding Department of Defense or other government situation.