View NSN Online: https://aerobasegroup.ae/nsn/8040-01-254-0300

## LOCTITE CORPORATION -- SPEEDBONDER (TM) 325 STRUCTURAL ADHESIVE \_\_\_\_\_\_ MSDS Safety Information \_\_\_\_\_\_ FSC: 8040 NIIN: 01-254-0300 MSDS Date: 04/15/1997 MSDS Num: CHKJP Product ID: SPEEDBONDER (TM) 325 STRUCTURAL ADHESIVE Responsible Party Cage: 05972 Name: LOCTITE CORPORATION Address: 1001 TROUT BROOK CROSSING ity: ROCKY HILL CT 06067-3910 Info Phone Number: 800-562-8483 FAX 860-571-5465 Emergency Phone Number: 860-571-5100 Preparer's Name: STEPHEN RIPETTO Proprietary Ind: Y Review Ind: Y Published: Y \_\_\_\_\_\_ Contractor Summary \_\_\_\_\_\_ Cage: 05972 Name: LOCTITE CORPORATION Address: 1001 TROUT BROOK CROSSING City: ROCKY HILL CT 06067-3910 Phone: 860-571-5100 \_\_\_\_\_\_ Item Description Information \_\_\_\_\_ Item Manager: GSA Item Name: ADHESIVE Unit of Issue: BT Quantitative Expression: 0000000100CC UI Container Qty: 0 \_\_\_\_\_\_ Ingredients \_\_\_\_\_\_ Name: \*\*\* PROPRIETARY \*\*\* \_\_\_\_\_\_ Health Hazards Data

LD50 LC50 Mixture: ORAL LD50 >5000 MG/KG;DERMAL >2000

Route Of Entry Inds - Inhalation: YES

Skin: YES Ingestion: YES

Carcinogenicity Inds - NTP: YES

IARC: YES OSHA: NO

Effects of Exposure: EYE: IRRITATION. SKIN: IRRITATION. INHAL: IRRITATION.

INGEST: MAY BE HARMFUL. MAY CAUSE KIDNEY/LIVER DAMAGE.

Explanation Of Carcinogenicity: SACCHARIN IS LISTED BY IARC AS POSSIBLE HUMAN

CARCINOGEN.

Signs And Symptions Of Overexposure: MAY CAUSE SEVERE DERMATITIS ON PROLONGED

## CONTACT IN SENSITIVE PEOPLE.

Medical Cond Aggravated By Exposure: ACRYLIC ACID UPPER RESPIRATORY/LUNG DISEASE, DERMATITIS.

First Aid: EYE: FLUSH W/WATER 15 MINUTES. GET MED AID. SKIN: WASH W/SOAP & CALM. GET FRESH AIR. GET MED AID. INGEST: DO NOT INDUCE VOMITING. KEEP CALM. GET MED AID.

\_\_\_\_\_\_

Handling and Disposal

\_\_\_\_\_

Spill Release Procedures: MAINTAIN ADEQUATE VENT. USE INERT

ABSORBENT. STORE IN

PARTLY FILLED CLOSED CONTAINER.

Waste Disposal Methods: INCINERATE FOLLOWING EPA/LOCAL REGS.

Handling And Storage Precautions: STORE <100F.

Other Precautions: AVOID PROLONGED SKIN CONTACT. KEEP AWAY FROM EYES. AVOID

PROLONGED BREATHING VAPORS.

\_\_\_\_\_\_

Fire and Explosion Hazard Information

\_\_\_\_\_

Flash Point Method: TCC

Flash Point Text: >200F,>93C

Lower Limits: 2.0 Upper Limits: 8.0

Extinguishing Media: CARBON DIOXIDE, FOAM, DRY CHEMICAL.

Fire Fighting Procedures: NONE

Unusual Fire/Explosion Hazard: NONE

\_\_\_\_\_

**Control Measures** 

\_\_\_\_\_\_

Respiratory Protection: NONE

Ventilation: SUFFICIENT TO MAINTAIN VAPORS BELOW TLV.

Protective Gloves: RUBBER OR PLASTIC

Eve Protection: SAFETY GLASSES OR GOGGLES

\_\_\_\_\_

Physical/C

nemical Properties
B.P. Text: >300F,>149C  Vapor Pres: <10 @ 80F  Spec Gravity: 1.11 @ 80F  Solubility in Water: SLIGHT  Appearance and Odor: YELLOWISH LIQUID, SHARP IRRITATING ODOR
Reactivity Data
Stability Indicator: YES Stability Condition To Avoid: NONE Materials To Avoid: NONE Hazardous Decomposition Products: IRRITATI NG ORGANIC VAPORS Hazardous Polymerization Indicator: NO Conditions To Avoid Polymerization: NONE
Toxicological Information
Ecological Information
======================================
======================================
======================================
======================================
Responsible Party Cage: 05972 Trans ID NO: 118565 Product ID: SPEEDBONDER (TM) 3 25 STRUCTURAL ADHESIVE MSDS Prepared Date: 04/15/1997 Review Date: 06/18/1998 MFN: 3 Multiple KIT Number: 0 Review IND: Y Unit Of Issue: BT Container QTY: 0
Detail DOT Information
DOT PSN Code: ZZZ DOT Proper Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION
Detail IMO Information

IMO PSN Code: ZZZ

IMO Proper Shipping Name: NOT REGULATED FOR THIS MODE OF TRANSPORTATION

\_\_\_\_\_

Detail IATA Information

\_\_\_\_\_

IATA PSN Code: ZZZ

IATA Proper Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION

\_\_\_\_\_\_

**Detail AFI Information** 

\_\_\_\_\_

AFI PSN Code: ZZZ

**AFI Proper** 

Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION

\_\_\_\_\_

**HAZCOM Label** 

\_\_\_\_\_\_

Product ID: SPEEDBONDER (TM) 325 STRUCTURAL ADHESIVE

Cage: 05972

Company Name: LOCTITE CORPORATION Street: 1001 TROUT BROOK CROSSING

City: ROCKY HILL CT Zipcode: 06067-3910

Health Emergency Phone: 860-571-5100

Label Required IND: Y

Date Of Label Review: 10/12/1999

Status Code: A
Origination Code: G
Hazard And Pr

ecautions: EYE: IRRITATION. SKIN: IRRITATION. INHAL: IRRITATION. INGEST: MAY BE HARMFUL. MAY CAUSE KIDNEY/LIVER DAMAGE.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever expressly or implied warrants, states, or intends said information to have any application, use or viability

by or to any person or persons outside the Department of Defense nor any person or persons contracting with any instrumentality of the United States of America and disclaims all liability for such use. Any person utilizing this instruction who is not a military or civilian employee of the United States of America should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation regardless of similarity

to a corresponding Department of Defense or other government situation.