View NSN Online: https://aerobasegroup.ae/nsn/1240-01-237-1584 TEXAS INSTRUMENTS INC DEFENSE SYSTEM & ELECTRONICS -- 2844491-1,OPTICAL,BENCH ASSEMBLY -- 1240-01-237-1584 ============= Product Identification ================= Product ID:2844491-1, OPTICAL, BENCH ASSEMBLY MSDS Date:09/03/1999 FSC:1240 NIIN:01-237-1584 Status Code:A MSDS Number: CJLMH === Responsible Party === Company Name: TEXAS INSTRUMENTS INC DEFENSE SYSTEM & ELECTRONICS Address:8505 FOREST LN Box:660246 City:DALLA S State:TX ZIP:75266-0246 Country:US Emergency Phone Num:804-279-4321 Preparer's Name: DSCR; VBA CAGE:96214 === Contractor Identification === Company Name: TEXAS INSTRUMENTS INC DEFENSE SYSTEM & ELECTRONICS Address:8505 FOREST LN Box:660246 City: DALLAS State:TX ZIP:75266-0246 Country:US Contract Num: DAAA09-84-G-0020-0012 CAGE:96214

======= Composition/Information on Ingredients ========

Ingred Name: THORIUM FLUORIDE 232

============ Hazards Identification ===========

| Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Health Hazards Acute and Chronic:THE OPTICAL, BENCH ASSEMBLY IS NOT CONSIDERED HAZARDOUS BY OSHA. |
|--|
| ====================================== |
| First Aid:NONE REQUIRED UNDER NORMAL CIRCUMSTANCES. |
| ====================================== |
| Extinguishing Media:USE MEDIA APPROPRIATE FOR SURROUNDING FIRE. Fire Fighting Procedures:USE PROCEDURES APPROPRIATE FOR SURROUNDING FIRE. |
| Unu sual Fire/Explosion Hazard:NONE |
| ========= Accidental Release Measures ========== |
| Neutralizing Agent:NONE |
| ====================================== |
| Handling and Storage Precautions:THE NORMAL CARE REQUIRED IN HANDLING AND STORINGOPTCAL LENSES SHOULD ALSO SUFFICE FOR THIS ITEM. Other Precautions:NONE. |
| ====== Exposure Controls/Personal Protection ======== |
| Respiratory Protection:NONE REQUIRED UNDER NORMAL USAGE. Ventilation:NORMAL VENTILATION ADEQUATE. Protective Gloves:NONE NORMALLY REQUIRED. Eye Protection:NONE NORMALLY REQUIRED. Other Protective Equipment:NONE. Work Hygienic Practices:STANDARD. Supplemental Safety and Health |
| THIS ITEM CONTAINS A RADIOACTIVE ISOTOPE, THORIUM FLUORIDE 232, WITH A |

THIS ITEM CONTAINS A RADIOACTIVE ISOTOPE, THORIUM FLUORIDE 232, WITH A RADIOACTIVITY OF 0.0003 MICRO CURIES. NO MSDS IS REQUIRED FOR THE OPTICAL, BENCH ASSEMBLY SINCE THE QUANTITY OF RADIOACTIVE MATER IAL IS WITHIN THE "EXCEPTED QUANTITY" FOR INSTRUMENTS AND ARTICLES, 49CFR 173.423,

| AND NOT CONSIDERED HAZARDOUS BY OSHA. |
|--|
| ========= Physical/Chemical Properties ========== |
| HCC:A2 Solubility in Water:N/AP |
| ======== Stability and Reactivity Data ========= |
| Stability Indicator/Materials to Avoid:YES |
| ========= Ecological Information =========== |
| Ecological:DISPOSAL OF ANY PARTS CONTAINING RADIOACTIVE MATERIAL MUST BE TRANSFERRED TO A LICENSED RADIOACTIVE MATERIAL DISPOSAL FIRM. |
| ======== Disposal Con siderations ==================================== |
| Waste Disposal Methods:THORIUM FLUORIDE CONTAINING ITEMS REMOVED FROM THE OPTICAL,BENCH ASSEMBLY MUST BE TRANSFERRED TO A LICENSED RADIOACTIVE MATERIAL DISPOSAL FIRM FOR DISPOSAL |
| ======== MSDS Transport Information ========== |
| Transport Information:PROPER SHIPPING NAME FOR THIS ITEM IS:"RADIOACTIVE MATERIAL,EXCEPTED PACKAGE-INSTRUMENTS OR ARTICLES UN2910. |

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.