View NSN Online: https://aerobasegroup.com/nsn/8040-00-016-8662

Product ID: EA 934 NA PART A MSDS Date:08/01/1991 FSC:8040 NIIN:00-016-8662 Kit Part:Y MSDS Number: BCVJZ === Responsible Party === **Company Name: DEXTER ADHESIVES & STRUCTURAL MATERIALS DIV** Address:2850 WILLOW PASS RD City:PITTSBURG State:CA ZIP:94565-0031 Country:US Info Phone Num :415-687-4201, X262 Emergency Phone Num:800-424-9300, 202-483-7616 Preparer's Name: MSDS DEPARTMENT CAGE:33564 === Contractor Identification === **Company Name: DEXTER CORPORATION ADHESIVE & COATING SYSTEMS** Address:2850 WILLOW PASS ROAD Box:312 **City:BAY POINT** State:CA ZIP:94565-3299 Country:US Phone:202-483-7616 CAGE:33564

Ingred Name:NO INGREDIENT FOR THIS FORMULATION_INGREDIENT

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:ACUTE- MAY CAUSE IRRITATION OF EYES, SKIN AND RESPIRATORY TRACT. MAY BE HARMFUL IF SWALLOWED. CHRONIC-SKIN SENSITIZATION. Effects of Overexposure:SKIN AND EYE IRRITATION; SKIN RASH. Medical Cond Aggravated by Exposure:SKIN DISEASES.

First Aid:INHALATION:REMO

VE TO FRESH AIR, PROVIDE CPR/OXYGEN IF NEEDED. EYE CONTACT:FLUSH WITH WATER FOR 15 MINUTES. GET MEDICAL HELP. SKIN CONTACT:WASH WITH SOAP AND WATER. GET MED ATTENTION IF SYMPTOMS PERSIS T. INGESTION:DO NOT INDUCE VOMITING, DRINK 1-2 GLASSES OF WATER. GET MEDICAL HELP IMMEDIATELY.
======================================
Extinguishing Media:DRY CHEMICAL, HALON, WATER SPRY, FOAM OR FOG. Fire Fighting Procedures:FIRE FIGHTERS SHOULD WEAR PROTECTIVE CLOT HING
AND SELF-CONTAINED BREATHING APPARATUS. Unusual Fire/Explosion Hazard:DENSE SMOKE AND TOXIC GASES MAY BE LIBERATED.
======================================
Spill Release Procedures: USE PROPER PERSONAL PROTECTION; SCRAPE UP OR WIPE UP AND RECOVER FOR PROPER DISPOSAL.
======================================
Handling and Storage Precautions:STORE IN COOL,DRY AND WELL VENTILATED.KEEP AWAY FROM HEAT,OPEN FLAME. MAY BE STO RED AT 40F FOR UPTO 12 MONTHS.
Other Precautions:EMPTY CONTAINERS RETAIN RESIDUE. DO NOT PRESSURIZE, CUT, WELD OR EXPOSE TO HEAT, FLAME, STATIC ELECTRICITY, OR OTHER SOURCES OF IGNITION; THEY MAY EXPLODE AND CAUSE INJURY.
========= Exposure Controls/Personal Protection ====================================
Respiratory Protection:USE NIOSH APPROVED RESPIRATOR FOR ORG.VAPORS/ DUST IF ABOVE TLV. Ventilation:PROVIDE LOCAL EXHAUST TO MAINTN 1
Spec Gravity:1.59 Evaporation Rate & amp; Reference:NEGLIGI BLE
Solubility in Water:NEGLIGIBLE Appearance and Odor:VISCOUS GREY PASTE WITH SLIGHT ODOR
======================================
Stability Indicator/Materials to Avoid:YES STRONG OXIDIZING AGENTS; STRONG LEWIS OR MINERAL ACIDS. Stability Condition to Avoid:EXTREME HEAT. AVOID MIXING PART A AND PART B IN BATCHES GREATER THAN 1 LBS. DO NOT HEAT MIXED ADHESIVE ABOVE 125F.
Hazardous Decomposition Products:CO, NOX, ALDEHYDES, ACIDS, UNKNOWN ORGANICS. Condit

ions to Avoid Polymerization:AVOID MIXING RESIN & CURING AGENT IN BATCH >1 LB

Waste Disposal Methods:DISPOSE OF COLLECTED MATERIALS IN ACCORDANCE WITH LOCAL,STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied,

warrants this information to be accurate and

disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.