

ELECTRICAL UTILITIES CO -- 1A9Z10301 -- 5910-00-146-4793

===== Product Identification =====

Product ID:1A9Z10301
MSDS Date:01/01/1985
FSC:5910
NIIN:00-146-4793
MSDS Number: BDCJR
=== Responsible Party ===
Company Name:ELECTRICAL UTILITIES CO
Address:1 INDUSTRIAL DR
Box:97
City:SNOW HILL
State:NC
ZIP:28580-0453
Country:US
Emergency Phone Num:NONE
CAGE:01102

=== Contractor Identification ===

Company
Name:CAPTRON INC
Address:1 INDUSTRIAL DR
Box:97
City:SNOW HILL
State:NC
ZIP:28580-0453
Country:US
Phone:919-747-5943
CAGE:81133
Company Name:ELECTRICAL UTILITIES CO.
Box:97
CAGE:01102

===== Composition/Information on Ingredients =====

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)
CAS:1336-36-3
RTECS #:TQ1350000
EPA Rpt Qty:1 LB
DOT Rpt Qty:1 LB

===== Hazards Identification =====

Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,I

NTTESTINE.CAUSES

CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)

===== First Aid Measures =====

First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR.AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UNC ONSCIOUS PERSON VOMIT.

===== Accidental Release Measures =====

Spill Release Procedures:USE ABSORBENT & DIKES TO PREVENT RUNOFF.ISOLATE & NOTIFY PROPER AUTHORITIES.

===== Handling and Storage =====

Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD
Ventilation:LOCAL EXHAUST
Protective Gloves:RUBBER-IMPERV
Eye Protection:GOGGLES,FACE SHIELD
Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT
Supplemental Safety and Health
OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.

===== Physical/Chemical Properties =====

HCC:V1
Appearance and Odor:LIGHT STRAW-COLORED LIQUID,AROMATIC ODOR

===== Stability and Reactivity Data =====

STRONG OXIDIZERS

===== Disposal Considerations =====

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH
TE

TEMPERATURE INCINERATION. ONLY APPROVED DISPOSAL OPERATOR
PERMITTED..

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.