

GENERAL ELECTRIC CO. -- 25F474 -- 5910-00-187-4004

===== Product Identification =====

Product ID:25F474  
MSDS Date:01/01/1985  
FSC:5910  
NIIN:00-187-4004  
MSDS Number: BDHFY  
=== Responsible Party ===  
Company Name:GENERAL ELECTRIC CO.  
Address:3135 EASTON TURNPIKE  
City:FAIRFIELD  
State:CT  
ZIP:06431  
Country:US  
Info Phone Num:800-626-2000  
Emergency Phone Num:800-626-2000  
CAGE:24446  
=== Contractor Identification ===  
Company Name:GENERAL ELECTRIC CO  
Address:3135 EASTON TURNPIKE  
Box:City:FAIRFIELD  
State:CT  
ZIP:06431  
Country:US  
Phone:800-626-2000/800-626-2004 (CHRIS)  
CAGE:24446

===== Composition/Information on Ingredients =====

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)  
CAS:1336-36-3  
RTECS #:TQ1350000  
EPA Rpt Qty:1 LB  
DOT Rpt Qty:1 LB

===== Hazards Identification =====

Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,INTESTINE.CAUS

ES

CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)

===== First Aid Measures =====

First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR. AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UN CONSCIOUS PERSON VOMIT.

===== Accidental Release Measures =====

Spill Release Procedures:USE ABSORBENT & DIKES TO PREVENT RUNOFF.ISOLATE & NOTIFY PROPER AUTHORITIES.

===== Handling and Storage =====

Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD  
Ventilation:LOCAL EXHAUST  
Protective Gloves:RUBBER-IMPERV  
Eye Protection:GOGGLES,FACE SHEILD  
Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT  
Su  
pplemental Safety and Health  
OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.

===== Physical/Chemical Properties =====

HCC:V1  
Appearance and Odor:LIGHT STRAW-COLORED LIQUID,AROMATIC ODOR

===== Stability and Reactivity Data =====

STRONG OXIDIZERS

===== Disposal Considerations =====

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPERATURE IN

CINERATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies):  
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.