## View NSN Online: https://aerobasegroup.ae/nsn/5910-00-706-5945 CORNELL-DUBILIER ELEC.DIV. OF FED.PAC.ELEC.CO. -- CRA3015 -- 5910-00-706-5945 Product ID:CRA3015 MSDS Date:01/01/1985 FSC:5910 NIIN:00-706-5945 MSDS Number: BFLZQ === Responsible Party === Company Name: CORNELL-DUBILIER ELEC.DIV. OF FED.PAC.ELEC.CO. Address: ONE INTERCHANGE PLZ City:WAYNE State:NJ ZIP:07470 Country:US Emergency Phone Num:201-694-8600 CAGE:14655 Contractor Identification === Company Name: CORNELL-DUBILIER ELECTRONICS Address: ONE INTERCHANGE PLZ Box:City:WAYNE State:NJ ZIP:07470 Country:US Phone:201-694-8600 CAGE:14655 ======= Composition/Information on Ingredients ======== Ingred Name: POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)

CAS:1336-36-3

RTECS #:TQ1350000 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Effects of Overexposure: ABSORBED THRU SKIN, LUNGS, INTESTINE.

CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)
======================================
First Aid:EYES:FLUSH W/WATER IMMED.SKIN:WASH W/SOAP IMMED.INHAL:REMOVE TO FRESH AIR.GIVE ART.RESPIR. AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UNCONSCIOUS PE RSON VOMIT.
======== Accidental Release Measures ==========
Spill Release Procedures:USE ABSORBENT & DIKES TO PREV
RUNOFF.ISOLATE & NOTIFY PROPER AUTHORITIES.
============= Handling and Storage =============
Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD Ventilation:LOCAL EXHAUST Protective Gloves:RUBBER-IMPERV Eye Protection:GOGGLES,FACE SHIELD Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT Supplement al Safety and Health OVEREXPOS:CAN CAUSE FORMATION OF CYSTS.CAUSES STILLBIRTHS.IRRITATES EYES,NOSE,THROAT.
======== Physical/Chemical Properties ==========
HCC:Z3 Appearance and Odor:LIGHT STRAW COLORED LIQUID,AROMATIC ODOR
========= Stability and Reactivity Data ==========
STRONG OXIDIZERS
======= Disposal Considerations ==========
Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPERATURE INCINERATI

**CAUSES** 

## ON.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.