

COURTAULDS AEROSPACE INC -- PR-810 RUBBER COMPOUND SOLUTION -- 8030-00-721-9473

=====  
Product Identification  
=====

Product ID:PR-810 RUBBER COMPOUND SOLUTION

MSDS Date:01/08/1988

FSC:8030

NIIN:00-721-9473

MSDS Number: BFMGW

=== Responsible Party ===

Company Name:COURTAULDS AEROSPACE INC

Address:757 CALIFORNIA ST

Box:1800

City:GLENDALE

State:CA

ZIP:91203

Country:US

Info Phone Num:818-549-7973

Emerg

ency Phone Num:818-549-7973

Preparer's Name:AS

CAGE:83574

=== Contractor Identification ===

Company Name:PRC-DESOTO INTERNATIONAL, INC. A PPG INDUSTRIES COMPANY

Address:5430 SAN FERNANDO RD

Box:1800

City:GLENDALE

State:CA

ZIP:91209

Country:US

Phone:818-240-2060

CAGE:83574

=====  
Composition/Information on Ingredients  
=====

Ingred Name:NO INGREDIENT FOR THIS FORMULATION\_INGREDIENT

=====  
Hazards Identification  
=====

LD50 LC50 Mixture:ORAL RAT

LD50 IS NOT KNOWN

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:PRODUCT MAY BE IRRITATING TO BODY TISSUES. IT MAY CAUSE LIVER AND/OR KIDNEY DAMAGE.

Explanation of Carcinogenicity:NONE OF THE COMPOUNDS IN THIS PRODUCT IS LISTED BY IARC, NTP, OR OSHA AS A CARCINOGEN.

Effects of Overexposure:EYE:IRRITATION. SKIN:LOCAL IRRITATION. MAY CAUSE DERMATITIS IN SENSITIZED INDIVIDUALS. INHALED:RESPIRATORY

IRRITATION. LEADING TO HEADACHE,DIZZINESS, AND UNCONSCIOUSNESS. INGESTED:NAUSEA,VOMITING,P OSSIBLE LIVER AND/OR KIDNEY DAMAGE.

Medical Cond Aggravated by Exposure:PEOPLE WHO HAVE DEVELOPED A SENSITIVITY TO THIS MATERIAL MAY EXPERIENCE ALLERGIC DERMATITIS.

===== First Aid Measures =====

First Aid:EYE:FLUSH W/WATER 15 MIN, HOLD LIDS OPEN. SKIN:WASH WITH SOAP & WATER. REMOVE CONTAMINATED CLOTHING AND LAUNDRER BEFORE REUSE. INHALE

D:REMOVE TO FRESH AIR. RESTORE BREATHING IF NECESSARY. INGESTED:DO NOT INDUCE VOMITING. GIVE 2 LARGE GLASSES OF MILK OR WATER AND GET IMMEDIATE MEDICAL CARE. GIVE NOTHING BY MOUTH IF UNCONSCIOUS. IF IRRITATION PERSISTS OR IS SEVERE,SEE A DOCTOR.

===== Fire Fighting Measures =====

Flash Point Method:PMCC

Flash Point:22.0F,-5.6C

Lower Limits:1.8

Upper Limits:10.6

Extinguishing Media:USE CARBON DIOXIDE, FOAM, DRY CHEMICAL, OR WATER FOG.

Fir

e Fighting Procedures:FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA & FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE.

Unusual Fire/Explosion Hazard:FIRE OR EXCESSIVE HEAT MAY CAUSE PRODUCTION OF HAZARDOUS DECOMPOSITION PRODUCTS AND/OR EXPLOSION OF CONTAINERS.

===== Accidental Release Measures =====

Spill Release Procedures:WIPE/SOAK UP WITH CLOTH OR PAPER TOWEL OR INERT ABSORBENT. P

UT IN DISPOSAL CONTAINER. REMOVE RESIDUE WITH  
1,1,1-TRICHLOROETHANE.

Neutralizing Agent:NONE

=====  
Handling and Storage  
=====

Handling and Storage Precautions:STORE IN A COOL, DRY, WELL VENTILATED  
AREA. KEEP CONTAINERS TIGHTLY CLOSED WHEN NOT IN USE. PROTECT  
CONTAINERS FROM PHYSICAL DAMAGE.

Other Precautions:NONE

=====  
Exposure Controls/Personal Protection  
=====

Respiratory Protection:RESPIRATOR WILL NOT NORMALLY BE NECESSARY.  
USE

NIOSH/MSHA APPROVED AIR SUPPLIED RESPIRATOR OR RESPIRATOR FOR  
ORGANIC VAPOR IF EXPOSURE IS ABOVE THE TLV/PEL. SEE 29 CFR 1910.134  
FOR REGULATIONS PERTAINING TO RESPIRATOR USE.

Ventilation:GENERAL ROOM VENTILATION IS NORMALLY ADEQUATE. USE LOCAL  
EXHAUST IF NECESSARY TO CONTROL EXPOSURE BELOW PEL/TLV.

Protective Gloves:SOLVENT RESISTANT

Eye Protection:SAFETY GLASSES OR GOGGLES

Other Protective Equipment:EYE WASH STATION AND SAFETY SHOWER.  
INDUSTRIAL-TYPE WORK CLOTHING AND  
APRON AS REQUIRED.

Work Hygienic Practices:USE GOOD CHEMICAL HYGIENE PRACTICE. AVOID  
UNNECESSARY CONTACT.

Supplemental Safety and Health

MSDS I.D. NO. MS2669B01.

=====  
Physical/Chemical Properties  
=====

HCC:F2

Vapor Density:2.42

Spec Gravity:1.04

pH:UNKNON

Evaporation Rate & Reference:3.8 (MEK)

Solubility in Water:SLIGHT

Appearance and Odor:NOT GIVEN BY MFR

Percent Volatiles by Volume:40.9

=====  
Stability and Reactivity Data  
=====

Stability Indicator/Materials to Avoid: YES

STRONG OXIDIZING AGENTS, AMINES

Stability Condition to Avoid: HIGH TEMPERATURES, SPARKS, AND OPEN FLAMES

Hazardous Decomposition Products: CARBON MONOXIDE, CARBON  
DIOXIDE, NITROGEN OXIDES, POSSIBLY TRACES OF HCN

===== Disposal Considerations =====

Waste Disposal Methods: DISPOSE I/A/W ALL FEDERAL, STATE AND LOCAL  
REGULATIONS. WASTE NO. D-001

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.