View NSN Online: https://aerobasegroup.com/nsn/8030-00-855-5015

3M COMPANY, ADHESIVE COATING & SEALANT DIV. -- EC-1063 ACCELERATOR -- 8030-00-855-5015

Product ID:EC-1063 ACCELERATOR

MSDS Date:01/01/1987

FSC:8030

NIIN:00-855-5015

MSDS Number: BFSWZ === Responsible Party ===

Company Name: 3M COMPANY, ADHESIVE COATING & SEALANT DIV.

Address:3M CENTER

City:ST. PAUL State:MN

ZIP:55144-1000 Country:US

Info Phone Num:612-733-1110

Em

ergency Phone Num:612-733-1110

CAGE:04963

=== Contractor Identification ===

Company Name: 3M MINNESOTA MINING AND MFG CO ADHESIVES SEALERS DIV

Address:3M CTR Box:City:SAINT PAUL

State:MN

ZIP:55144-1000 Country:US

Phone:800-364-3577/651-737-6501(24 HOURS)

CAGE:04963

====== Composition/Information on Ingredients ========

Ingred Name:LEAD PEROXIDE (LEAD DIOXIDE), (OSHA PEL FROM 29CFR

1910.1025) CAS:1309-60-0

RTECS #:OG0700000 Fraction by Wt: 50%.

OSHA PEL:0.05 MG/M3 (PB)

ACGIH TL

Ingred Name:DIBUTYL PHTHALATE (SARA III) CAS:84-74-2 RTECS #:TI0875000 OSHA PEL:5 MG/M3 ACGIH TLV:5 MG/M3; 9192 EPA Rpt Qty:10 LBS DOT Rpt Qty:10 LBS
Ingred Name:STEARIC ACID (COMBINED W/DIBUTYL PHTHALATE.COMPRISES APPROX. 50% OF PRODUCT) CAS:57-11-4
RTECS #:WI2800000
========== Hazards Identification ===========
Effects of Overexposure:CHRONIC EXPOSURE CAN LEAD TO LEAD POISONING. AVOID EYE & SKIN CONTACT.
======================================
Aid Measures ==============
First Aid:EYE: FLUSH W/ PLENTY OF WATER & CALL A PHYSICIAN.
======================================
Extinguishing Media:CO*2, FOAM, DRY CHEMICAL Fire Fighting Procedures:NONE Unusual Fire/Explosion Hazard:NONE
========= Accidental Release Measures =========
Spill Release Procedures:COLLECT SPILLED MATERIAL USING ABSORBENT MATERIAL. CLEAN UP RESIDUE & AREA.
======================================
Handling and Storage Precautions:AVOID EYE CONTACT 6 PROLONGED SKIN CONTACT. WASH HANDS BEFORE EATING OR SMOKING. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE.
====== Exposure Controls/Personal Protection ========
Ventilation:MFR STATES: MECHANICAL VENTILATION ADEQUATE Protective Gloves:IMPERV. GLOVES Eye Protection:SAFETY GLASSES Supplemental Safety and Health PART B OF TWO PART EC-801 SEALANT KIT.STORE WITH PART A AND DO NOT SEPARATE. ENTRY B

V:0.15 MG/M3(PB); 8990

ASIS: MSDS FOR NSN 8030-00-537-7925 ENTERED APRIL 1986.QTY: N/K KEY1:D1
========= Physical/Chemical Properties =========
HCC:D1 Spec Gravity:1.9 Appearance and Odor:DARK BROWN PASTE Percent Volatiles by Volume:0.0
======== Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES Hazardous Decomposition Products:CO, CO*2, & SMOKE PARTICLES

======== Disposal Considerations ==============

Waste Disposal M

ethods:MFR RECM: LG QTY--DISPOSE IN SECURE LANDFILL AT HAZARDOUS WASTE MANAGEMENT FACILITY. CONSULT APPROPRIATE FED., STATE & LOCAL CODES. SM QTY--DISPOSE OF INDIV EMPTY CONTAINERS IN A SANITARY LANDFILL IAW FED,. STATE & LOCAL CODES.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.