

RAYTHEON CO. FOUNDRY AVE. WALTHAM MA. 02254 -- QKA-1432 -- 5865-01-021-0758

=====
Product Identification
=====

Product ID:QKA-1432

MSDS Date:01/01/1985

FSC:5865

NIIN:01-021-0758

MSDS Number: BGDZV

=== Responsible Party ===

Company Name:RAYTHEON CO. FOUNDRY AVE. WALTHAM MA. 02254

Emergency Phone Num:419/862-2745X148

CAGE:MO579

=== Contractor Identification ===

Company Name:RAYTHEON CO,EXECUTIVE OFFICES

Address:141 SPRING ST

Box:City:LEXINGTON

State:MA

ZIP:02173-7801

Country:US

Phone:617-862-6600

CAGE:49956

Company Name:RAYTHEON CO. FOUNDRY AVE. WALTHAM MA. 02254

CAGE:MO579

=====
Composition/Information on Ingredients
=====

Ingred Name:BERYLLIUM OXIDE (AS BERYLLIUM)

CAS:1304-56-9

RTECS #:DS4025000

OSHA PEL:0.002 MG/M3; C,0.005

ACGIH TLV:0.002 MG/M3; A2;8990

=====
Hazards Identification
=====

Effects of Overexposure:ACUTE:PNEUMONITIS.

ACUTE LOCAL: IRRITANT

CHRONIC: BERYLLIOSIS. POSSIBLE CARCINOGEN.

=====
First Aid Measures
=====

First Aid:ALL B O IMPLANTED IN SKIN MUST BE REMOVED IMEDIATELY. WASH THOROUGHLY WITH WATER. UPON INHALATION OBTAIN X-RAY.

=====
Accidental Release Measures
=====

Spill Release Procedures:CONTAIN. HIGHLY TOXIC BY INHALATION.

RESPIRATORY PROTECTION REQUIRED IF MATERIAL BECOMES AIRBORNE.

CLEAN UP WITH WET M

OP OR WET RAGS. DO NOT DRY SWEEP OR CAUSE B
O TO BECOME AIRBORNE. ITEM IS HAZARD ONLY IF TUBE IS BROKEN AND
SPRE

=====
Handling and Storage
=====

Handling and Storage Precautions:USE GLOVES AND PROTECTIVE CLOTHING. DO
NOT TAKE CONTAMINATED ITEMS HOME. KEEP CONTAINERS TIGHTLY
CLOSED.

Other Precautions:MATERIAL IS HAZARDOUS ONLY IF TUBE BROKEN AND B O
IS SPREAD.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:ONLY IF MATERIAL BECOMES AIRBORNE.

Ventilation:YES

Protective Gloves:YES

Eye Protection:FACESHIELD

Supplemental Safety and Health

BRUSH WELLMAN, ELMORE OHIO SUPPLIES RAYTHEON WITH B O TO MFG TUBE.

=====
Physical/Chemical Properties
=====

HCC:M1

Boiling Pt:B.P. Text:3960 C.

Spec Gravity:3.016

Appearance and Odor:WHITE POWDER.

=====
Stability and Reactivity Data
=====

Stability Indicator/Materials to Avoid:YES

St

ability Condition to Avoid:SKIN CONTACT OR INHALATION.

=====
Disposal Considerations
=====

Waste Disposal Methods:IN ACCORDANCE WITH ALL LOCAL, STATE AND FEDERAL
REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclai

ms all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.