View NSN Online: https://aerobasegroup.ae/nsn/6850-01-121-0952

SHERWIN INC -- DUB 1-CHECK D 113 G DEVELOPER -- 6850-01-121-0952

Product ID:DUB 1-CHECK D 113 G DEVELOPER MSDS Date:01/01/1988 FSC:6850 NIIN:01-121-0952 MSDS Number: BGMVG === Responsible Party === **Company Name:SHERWIN INC** Address:5530 BORWICK AVE **City:SOUTH GATE** State:CA ZIP:90280-7402 Country:US Info Phone Num:213-861-6324 Emergency Phone Num:213-861-6324 CAGE: 21405 === Contractor Identification === Company Name: SHERWIN INC. Address:5530 BORWICK AVE. **City:SOUTH GATE** State:CA ZIP:90280-7402 Country:US Phone:562-861-6324/FAX 923-8370 CAGE:21405

Other REC Limits:NONE SPECIFIED

Ingred Name:NON-IONIC SURFACTANT Fraction by Wt: 14.0%

Ingred Name:SODIUM NITRITE (SARA III)

CAS:7632-00-0

RTECS #:RA1225000 Fraction by Wt: 90.0%

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:ACUTE & CHRONIC-NUISANCE DUST Effects of Overexposure:RESPIRATORY TRACT IRRITATION.

First Aid:EYE:IMMEDIATELY FLUSH WITH WATER AT LEAST FOR 15 MINUTES.SEE A PHYSICIAN.INGESTION:GIVE TWO GLASSES OF WATER AND INDUCE VOMITING.

================== Fire Fighting Measures

Flash Point:NOT FLAMMABLE Extinguishing Media:STANDARD FIREFIGHTING AGENTS, WATER FOG, CARBON DIOXIDE, DRY CHEMICAL, FOAM. Fire Fighting Procedures:NONE SPECIFIED BY MANUFACTURER. Unusual Fire/Explosion Hazard:SODIUM NITRITE IS AN OXIDIZING AGENT; IT

CAN SUPPLY OXYGEN TO ACCELERATE OR STIMULATE FIRE.

Spill Release Procedures:VACUUM OR SWEEP AS DUST. PLACE IN APPROVED CONTAINER. Neutralizing Agent:NOT APPLICABLE.

Handling and Storage Precautions:STORE IN TIGHTLY CLOSED CONTAINERS, AWAY FROM HEAT, ACIDS AND COMBUSTIBLES. Other Precautions:NONE GIVEN.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection:USE NIOSH-APPROVED NUISANCE MASK. Ventilation:DUST EXHAUST AT POINT OF USE. Protective Gloves:STANDARD WORK GLOVES Eye Protection:CHEMICAL GOGGLES Other Protective Equipmen t:NONE NORMALLY REQUIRED. Work Hygienic Practices:AVOID BREATHING DUST. KEEP AREA FREE OF DUST. Supplemental Safety and Health

HCC:N1 Solubility in Water:50 G/100 ML @ 25 C Appearance and Odor:WHITE ODORLESS POWDER

Stability Indicator/Materials to Avoid:YES

ACIDS, REDUCING AGENTS, AMMONIA, COMBUSTIBLE MATERIALS SUCH AS WOOD OR CHARCOAL OR ORGANIC MATERI ALS. Stability Condition to Avoid:HIGH TEMPERATURES ABOVE 575 F.

Hazardous Decomposition Products:EMITS ACRID FUMES WHEN HEATED TO DECOMPOSITION.

Waste Disposal Methods:DISPOSE OF IN COMPLIANCE WITH ALL LOCAL, STATE, AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of Am erica in no manner whatsoever,

expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.