View NSN Online: https://aerobasegroup.com/nsn/8010-00-527-2507

Product ID:LACQUER, ACRYLIC, N/C, GLOSS BLACK, 17038

MSDS Date:03/20/1991

FSC:8010

NIIN:00-527-2507

MSDS Number: BKJLB === Responsible Party ===

Company Name: PRATT AND LAMBERT INC

Address:16116 E 13TH ST

Box:2153 City:WICHITA

State:KS ZIP:67201 Country:US

Info Phone Num:316-73

3-1361

Emergency Phone Num:716-873-6000 DOT EMER 8002553924

Preparer's Name:W A ELLISON

CAGE:61196

=== Contractor Identification ===

Company Name: PRATT AND LAMBERT INC

Box:6027

City:CLEVELAND

State:OH

ZIP:44101-1027 Country:US

Phone:216-566-2902

CAGE:61196

======= Composition/Information on Ingredients ========

Ingred Name: ISOBUTYL ACETATE (SARA III)

CAS:110-19-0

RTECS #:AI4025000 Fraction by Wt: 45%

Other REC Limits: NONE SPECIFIED

**OSHA PEL:150 PPM** 

ACGIH TLV:150 PPM; 9192

**EPA Rpt** 

Qty:5000 LBS

DOT Rpt Qty:5000 LBS

Ingred Name: ISOPROPYL ALCOHOL (SARA III)

CAS:67-63-0

RTECS #:NT8050000 Fraction by Wt: 5%

Other REC Limits: NONE SPECIFIED

OSHA PEL:400 PPM/500 STEL

ACGIH TLV:400 PPM/500STEL;9192

Ingred Name: NITROCELLULOSE (RESIN)

CAS:9004-70-0

RTECS #:WG2934500 Fraction by Wt: 10%

Other REC Limits: NONE SPECIFIED

Ingred Name: CARBON BLACK

CAS:1333-86-4

RTECS #:FF5800000 Fraction by Wt: < 5%

Other REC Limits: NONE SPECIFIED

OSHA PEL:3.5 MG/M3

ACGIH TLV:3.5 MG/M3; 9192

Ingred

Name: METHYL ISOBUTYL KETONE (SARA III)

CAS:108-10-1

RTECS #:SA9275000 Fraction by Wt: < 5%

Other REC Limits: NONE SPECIFIED

OSHA PEL:100 PPM/75 STEL

ACGIH TLV:50 PPM/75 STEL; 9293

EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:DI-SEC-OCTYL PHTHALATE (DI-2-ETHYLHEXYL-PHTHALATE) (SARA

III)

CAS:117-81-7

RTECS #:TI0350000 Fraction by Wt: 5%

Other REC Limits: NONE SPECIFIED

OSHA PEL:5 MG/M3/10 STEL ACGIH TLV:5 MG/M3; 9192

EPA Rpt Qty:100 LBS DOT Rpt Qty:100 LBS

Ingred Name: CYCLOHEXANONE

(SARA III) CAS:108-94-1 RTECS #:GW1050000 Fraction by Wt: 5% Other REC Limits: NONE SPECIFIED OSHA PEL:S, 50 PPM ACGIH TLV:S, 25 PPM; 9293 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS Ingred Name:VM&P NAPTHA (SOLVENT) (LFL: .9 UFL: 6.7) CAS:8030-30-6 RTECS #:DE3030000 Fraction by Wt: 5% Other REC Limits: NONE SPECIFIED OSHA PEL:300 PPM/400 PPM STEL ACGIH TLV:300 PPM / 1350 MG/M3 Ingred Name: METHYL ETHYL KETONE (2-BUTANONE) (MEK) (SARA III) CAS:78-93-3 RTECS #:EL6475000 Fraction by Wt: < 5% Other R **EC Limits:NONE SPECIFIED** OSHA PEL:200 PPM/300 STEL ACGIH TLV:200 PPM/300STEL 9192 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name: VOC: 5.21 LB/GL LESS WATER & NPRS\*; 625 G/L LESS WATER; CALCULATED (\*NEGLIGIBLY PHOTOCHEMICALLY REACTIVE MATERIALS)

RTECS #:9999999VO

Other REC Limits: NONE SPECIFIED

Ingred Name: VOC: 19.70 LB/GAL SOLIDS; 2364 G/L SOLIDS; CALCULATED

RTECS #:9999999VO

Other REC Limits: NONE SPECIFIED

========== Hazards Identification ===============

Repor

Health Hazards Acute and Chronic: INGEST/INHALE/EYE/SKIN: IRRITATION (GASTROINTESTINAL, NOSE, THROAT, EYE, SKIN). LUNG ASPIRATION MAY CAUSE CHEMICAL PNEUMONITIS, WHICH CAN BE FATAL. CENTRAL NERVOUS SYSTEM DEPRESSION. CORNEAL DAMAGE. S KIN ABSORPTION. OVEREXPOSURE: PERIPHERAL NEUROPATHY, PERMANENT BRAIN & NERVOUS SYSTEM DAMAGE. Explanation of Carcinogenicity:DI(2-ETHYLHEXYL)PHTHALATE IS LISTED AS A POTENTIAL CARCINOGEN BY THE NTP. Effects of Overexposure: INGEST: NAUSEA/VOMITING. INHALE: HEADACHES, DIZZINESS, NAUSEA, CONFUSION. First Aid:INGEST: DO NOT INDUCE VOMITING. CALL POISON CONTROL, EMERGENCY ROOM OR PHYSICIAN IMMEDIATELY, INHALE: REMOVE TO FRESH AIR IMMEDIATELY. GIVE ARTIFICIAL RESPIRATION IF NEEDED. KEEP WARM & QUIET. GET IMM EDIATE MEDICAL AID. EYE: FLUSH THOROUGHLY WITH LARGE AMOUNT OF WATER FOR 15 MIN. GET MEDICAL A ID. SKIN: REMOVE CONTAMINATED CLOTHES. WASH AFFECTED AREA WITH SOAP & WATER IMMEDIATELY. Flash Point:24.0F,-4.4C Autoignition Temp: Autoignition Temp Text: 572F Lower Limits:0.9 Upper Limits:13.0 Extinguishing Media: USE NFPA CLASS B(CO2, ALL PURPOSE DRY CHEMICAL OR ALCOHOL FOAM) FOR LIQUID FIRES. POLYMER FOAM PREFERRED FOR LARGE **FIRES** Fire Fighting Procedures: WATER MAY BE INEFFECTIVE, USE TO COOL **CONTAINERS** 

(FOG NOZZLE PREFERABLE) TO PREVENT PRESSURE BUILD-UP & AUTO- IGNITION OR EXPLOSION WHEN EXPOSED TO EXTREME HEAT Unusual Fire/Explosion Hazard:DURING EMERGENCY CONDITIONS, OVEREXPOSURE TO DECOMPOSITION PRODUCTS MAY CAUSE A HEALTH HAZARD. SYMPTOMS MAY NOT BE IMMEDIATELY APPARENT. GET MEDICAL ATTENTION.

========= Accidental Release Measures ============

Spill Release Procedures: KEEP SPECTATORS AWAY. ELIMINATE ALL IGNITE SOURCES. DIKE, CONTAIN & REMOVE WITH INERT M

ATERIAL (SAND, EARTH, ETC). USE COVERED METAL CONTAINERS FOR RECOVERY AND DISPOSAL. USE NON-SPARKING TOOLS. PREVE NT CONTAMINATION OF SEWERS, STREAMS & GROUNDWATER.
======================================
Handling and Storage Precautions:DO NOT STORE ABOVE 100F. LARGE QUANTITY STORAGE: COMPLY WITH OSHA 29CFR1910.106. DO NOT TAKE INTERNALLY. KEEP FROM CHILDREN. DO NOT REUSE CONTAINERS. Other Precautions:CONTAINERS SHOULD BE GROUNDED AND BONDED TO THE
RECEIVING CONTAINER. DO NOT WELD, BRAZE OR CUT ON EMPTY CONTAINER. NEVER USE PRESSURE TO EMPTY. DRUM IS NOT A PRESSURE VESSEL. KEEP CONTAINERS CLOSED WH EN NOT IN USE.
====== Exposure Controls/Personal Protection =========
Respiratory Protection:RESTRICTED AREA: NIOSH APPR'D CHEMICAL CARTRIDGE RESPIRATOR. SPRAYING: MECHANICAL PREFILTER MAY BE REQUIRED. CONFINED AREAS: NIOSH/MSHA APPROVED AIR SUPPLIED RESPIRATOR. EXCEEDED TLV AREA: NIOSH/MSHA APPROVED RESPIRATOR W/RIGHT FACTOR. /entilation:GENERAL DILUTION/LOCAL EXHAUST VENTILATION IN SUFFICIENT
VOLUME & PATTERN TO KEEP CONCENTRATIONS BELOW EXPOSURE LIMITS. Protective Gloves:REPEAT/PROLONG: IMPERMEABLE GLOVES. Eye Protection:SAFETY GLASSES W/SIDESHIELD, FACESHIELD. Other Protective Equipment:NOT LIKELY TO BE NEEDED. Supplemental Safety and Health
Physical/Chemical Properties
HCC:F2 Boiling Pt:B.P. Text:175 TO 314F Melt/Freeze Pt:M.P/F.P Text:-50F,- Melt/Freeze
Appearance and Odor:LIQUID, SOLVENT ODOR Percent Volatiles by Volume:73
======================================
Stability Indicator/Materials to Avoid:YES STRONG ACIDS OR ALKALINE MATERIALS.

Stability Condition to Avoid:AVOID EXCESS HEAT (> 100F) & IGNITION

## SOURCES. Hazardous Decomposition Products:BURNING, (INCLUDE HEAT BY

WELDING/CUTTING) PRODUCES SMOKE, CARBON MONOXIDE & CARBON DIOXIDE,
POSSIBLE NITROGEN OXIDE.

====== Disposal Considerations ===========

Waste Disposal Methods:DISPOSE IN ACCORDANCE WITH FEDERAL, STATE AND LOCAL REGULATIONS & LAWS. INCINERATE IN EPA FACILITY. DO NOT INCINERATE CLOSED CONTAINERS USE PRECAUTIONS FOR DISPOSAL OF FLAMMABLE MATERIAL-D001. USE HAZ ARDOUS WASTE LANDFILL FOR USED

ABSORBENTS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their

particular situation.