

BONDED PRODUCTS INC -- SPEC 20-20 PART B, MMM-A-1754 -- 8040-00-944-7292
===== Product Identification =====

Product ID:SPEC 20-20 PART B, MMM-A-1754

MSDS Date:05/01/1990

FSC:8040

NIIN:00-944-7292

Kit Part:Y

MSDS Number: BLVBM

=== Responsible Party ===

Company Name:BONDED PRODUCTS INC

Address:439 S BOLMAR ST

Box:39

City:WEST CHESTER

State:PA

ZIP:19382-4933

Country:US

Info Phone Num:215-696-9220

Em

ergency Phone Num:215-696-9220

Preparer's Name:A. NICHOLAS ROSA

CAGE:19092

=== Contractor Identification ===

Company Name:ABBEY COLOR INC DBA ABBEY PRODUCTS AND BONDED

Address:400 E TIOGA ST

Box:City:PHILADELPHIA

State:PA

ZIP:19134-1127

Country:US

Phone:215-739-9960

CAGE:19092

===== Composition/Information on Ingredients =====

Ingred Name:POLYAMIDE RESIN

CAS:68410-23-1

Other REC Limits:NONE SPECIFIED

Ingred Name:DICYANADIAMIDE

Other REC Limits:NONE SPECIFIED

Ingred Name:BYK

A520
Other REC Limits:NONE SPECIFIED

Ingred Name:CARBON BLACK
CAS:1333-86-4
RTECS #:FF5800000
Other REC Limits:NONE SPECIFIED
OSHA PEL:3.5 MG/M3
ACGIH TLV:3.5 MG/M3; 9192

Ingred Name:CALCIUM CARBONATE (MARBLE) (LIMESTONE)
CAS:1317-65-3
RTECS #:EV9580000
Other REC Limits:NONE SPECIFIED
OSHA PEL:15 MG/M3 TDUST
ACGIH TLV:10 MG/M3 TDUST; 9192

Ingred Name:BARIUM SULFATE
CAS:7727-43-7
RTECS #:CR0600000
Other REC Limits:NONE SPECIFIED
OSHA PEL:15 MG/M3 TDUST
ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred Name:SILICA GEL
CAS:112945-52-5
RTECS #:VV7310000
Other REC Limits:NONE SPECIFIED
OSHA PEL:6 MG/M3 TDUST
ACGIH TLV:10 MG/M3 TDUST

Ingred Name:FIBERFRAX HSA FIBER
Other REC Limits:NONE SPECIFIED

===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:INHALATION: MAY CAUSE HEADACHE. SKIN
AND EYES: MAY CAUSE MODERATE IRRITATION AND POSSIB

LE SENSITIZATION.

INGESTION: MAY CAUSE NAUSEA AND VOMITING.

Effects of Overexposure:NAUSEA AND VOMITING IF INGESTED. SKIN MAY ITCH AND BECOME PINK UPON CONTACT.

Medical Cond Aggravated by Exposure:ALLERGIES AND SKIN CONDITIONS.

===== First Aid Measures =====

First Aid:INHALATION: REMOVE PERSON TO FRESH AIR, GIVE OXTGEN AND ARTIFICIAL RESPIRATION IF NEEDED. SKIN: WASH WITH SOAP AND WATER. EYES: FLUSH WITH WATER FOR AT LEAST 15 MIN. SEE PHYSICIAN.

===== Fire Fighting Measures =====

Flash Point Method:COC

Flash Point:>250F,>121C

Extinguishing Media:FOAM, CARBON DIOXIDE, DRY CHEMICAL, WATER FOG.

Fire Fighting Procedures:CONTAINERS EXPOSED TO FIRE SHOULD BE KEPT COOL WITH WATER SPRAY, FIREFIGHTERS SHOULD WEAR SELF-CONTAINED BREATHING APPARATUS.

Unusual Fire/Explosion Hazard:THE PRODUCT SHOULD BE HANDLED AS A COMBUSTIBLE MATERIAL.

===== Accidental Release Measures =====

=====

Spill Release Procedures:CONTAIN SPILL. REMOVE ALL SOURCES OF IGNITION. VENTILATE AREA. ABSORB SPILLED PRODUCT AND SCRAPE UP FOR PROPER DISPOSAL. CLEAN UP CONTAMINATED AREA WITH SOAP AND WATER.

Neutralizing Agent:NONE

===== Handling and Storage =====

Handling and Storage Precautions:WORK IN A WILL-VENTILATED AREA. STORE IN A COOL AREA. AVOID FLAMES AND SPARKS.

Other Precautions:AVOID BREATHING VAPORS. LAUNDRER CONTAMINATED CLOTHING BEFORE REUSE. DISCARD CONTAMINATED SHOES AND LEATHER ARTICLES.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:NIOSH-APPROVED RESPIRATOR.

Ventilation:LOCAL EXHAUSE. GENERAL MECHANICAL VENTILATION.

Protective Gloves:IMPERVIOUS GLOVES.

Eye Protection:SPLASH-PROOF GOGGLES OR FACE SHIELD.

Other Protective Equipment:RUBBER APRON. USE NIOSH RESPIRATOR IF SANDING IS BEING DONE. SAFETY SPRAY OR SHOWER, AND EYEBATH.

Work Hygienic Practices:WASH THOROUGH

HLY AFTER HANDLING. PRACTICE GOOD

PERSONAL HYGIENE TO AVOID INHALATION, SKIN AND EYE CONTACT.

Supplemental Safety and Health

NONE

===== Physical/Chemical Properties =====

HCC:N1

Spec Gravity:1.7

Solubility in Water:SLIGHT

Appearance and Odor:BLACK PASTE, SLIGHT AMMONIA ODOR.

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

STRONG OXIDIZING AGENTS, NATURAL RUBBER.

Stability Condition to Avoid:STORAGE

AT TEMPERATURES OVER 110F.

Hazardous Decomposition Products:OXIDES OF CARBON AND NITROGEN, AND PHENOLICS.

===== Disposal Considerations =====

Waste Disposal Methods:REACT PART A WITH PART B. BURN IN AN INCINERATOR OR DISPOSE IN AN APPROVED AREA THAT COMPLIES WITH FEDERAL, STATE, AND LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Def

ense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.