Product ID:PC-31-625C BATTERY ELECTRICAL STORAGE, WET MSDS Date:04/15/1986 FSC:6140 NIIN:01-134-5413 MSDS Number: BPPNF === Responsible Party === Company Name: GNB INCORPORATED Address:1110 HIGHWAY 110 City:MENDOTA HEIGHTS State:MN ZIP:55118 Country:US Info Phone Num:612-681-5000 Em ergency Phone Num:612-681-5000 CAGE:OMM77 === Contractor Identification === **Company Name: BATTERY OUTLET INC** Address:1608 CAMPOSTELLA RD Box:City:CHESAPEAKE State:VA ZIP:23324 Country:US Phone:757-545-4442 CAGE:0FGN2 Company Name: CHICAGO INDUSTRIAL TRADING CO Address:1901 LANDMEIER RD Box:City:ELK GROVE VILLAGE State:IL ZIP:60007 Country:US Phone:708-981-0090 CAGE:0K4U5 Company Name: EXIDE TECHNOLOGIES INC CO, GNB INDUSTRIAL POWER DIV Address:829 PARKVIEW BOULEVARD Box:City:LOMBARD State:IL ZIP:60

148-3249 Country:US Phone:800-872-0471/630-691-7841 CAGE:88219 Company Name:GNB INCORPORATED Address:1110 HIGHWAY 110 City:MENDOTA HEIGHTS State:MN ZIP:55118 Country:US Phone:612-681-5000 CAGE:OMM77

Ingred Name:SULFURIC ACID (SARA III) CAS:7664-93-9 RTECS #:WS5600000 Fraction by Wt: 27% OSHA PEL:1 MG/CUM ACGIH TLV:1 MG/CUM; 9192 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:LEAD (SARA III) CAS:7439-92-1 RTECS #:OF75 25000 Fraction by Wt: 50% Other REC Limits:NONE RECOMMENDED OSHA PEL:0.05 MG/M3;1910.1025 ACGIH TLV:0.15 MG/M3;DUST 9293 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:ELECTROLYTE- ACUTE: BURNS, SEVERE IRRITATION OF SKIN & EYES, MOUTH, THROAT, ESOPHAGUS AND STOMACH; INFLAMMATION OF BRONCHIA

L MEMBRANES. CHRONIC: EROSION OF TEETH,
INFLAMMATION OF NOSE, THROAT AND BRON CHIAL TUBES.
Explanation of Carcinogenicity:NONE
Effects of Overexposure:INHALED: COUGHING, WHEEZING, SHORTNESS OF
BREATH. SKIN: BURNING SENSATION, BURNS, REDNESS, BLISTERS, PAIN.
EYES: PAIN, REDNESS, BLURRED VISION, TEARING. INGESTED: BURNS OF
MOUTH AND THROAT, SEVERE STO MACH PAIN, NAUSEA, VOMITING.
Medical Cond Aggravated by Exposure: EXPOSURE TO MISTS MAY CAUSE LUNG
DAMAGE AND AGGRAVATE PULMONARY
CONDITIONS.

First Aid:INHALED: REMOVE TO FRESH AIR. EYES: FLUSH WITH LOTS OF WATER FOR 15 MINUTES. SEE DOCTOR. SKIN: REMOVE CONTAMINATED CLOTHES. FLUSH WITH LOTS OF WATER FOR 15 MINUTES.

Extinguishing Media:USE CARBON DIOXIDE, FOAM, DRY CHEMICAL, OR WATER FOG.

Fire Fighting Procedures: FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA & FULL PRO

TECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE.

Unusual Fire/Explosion Hazard: ELECTROLYTE REACTS VIOLENTLY WITH WATER AND ORGANIC MATERIALS WITH EVOLUTION OF HEAT.

Spill Release Procedures:WEAR APPROPIATE PROTECTIVE EQUIPMENT. DILUTE CAUTIOUSLY WITH WATER. COVER WITH SODA ASH OR QUICKLIME. SCOOP UP AND PLACE IN APPROPIATE DISPOSAL CONTAINER. Neutralizing Agent:SODA ASH (SODIUM CARBONATE) OR QUICKLIME (CALCIUM OX IDE).

 Handling and Storage Precautions:STORE AWAY FROM IGNITION SOURCES AND COMBUSTIBLE MATERIALS.AVOID CONTACT WITH ORGANIC MATERIALS.
Other Precautions:KEEP TERMINALS COVERED IN PLASTIC CASE.AVOID SHORTING BATTERIES.

======= Exposure Controls/Personal Protection ===============

Respiratory Protection:NONE NORMALLY REQUIRED. NIOSH/MSHA-APPROVED CARTRIDGE RESPIRATOR FOR ACIDS OR FULL FACE MASK AS APPROPIATE

FOR EXPOSURE OF CONCERN WHEN TLV IS EXCEEDED. Ventilation: GENERAL (MECHANICAL) VENTILATION. LOCAL EXHAUST IN CONFINED AREAS. Protective Gloves: RUBBER Eye Protection:GOGGLES Other Protective Equipment: RUBBER APRON AND BOOTS. EYES WASH STATION AND SAFETY SHOWER. Work Hygienic Practices: WASH THOROUGHLY AFTER HANDLING. LAUNDER CONTAMINATED CLOTHES BEFORE REUSE. Supplemental Safety and Health THIS MSDS IS FOR ACID IN BATTERY. ADDITIONAL HAZARDS ASSOCIATED WITH THE LEAD CONTAINED IN THE BATTERY PLATES MAY BE PRESENT AT TIME OF DISPOSAL. HCC:C1 Appearance and Odor:BATTERY Stability Indicator/Materials to Avoid:YES COMBUSTIBLES, ORGANIC MATERIALS, STRONG REDUCING AGENTS. Stability Condition to Avoid: HIGH TEMPERATURES, SPARKS, AND OPEN FLAMES. OVERCHARGING. Hazardous Decomposition Products: SULFURIC ACID FUMES, SULFUR DIOXIDE, SULFUR TRIOXIDE, CARBON MONOXIDE.

Waste Disposal Methods:CONSULT YOUR LOCAL ENVIRONMENTAL OFFICER. DISPOSE OF IN ACCORDANCE WITH FEDERAL,STATE AND LOCAL ENVIRONMENTAL REGUALTIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrant s this information to be accurate and

disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.