

ROCKWELL INTERNATIONAL CORP GOVERNMENT PRODUCTS -- A-19-3222-H-1074 --  
2530-01-337-7293

=====  
===== Product Identification =====

Product ID:A-19-3222-H-1074

MSDS Date:01/28/1993

FSC:2530

NIIN:01-337-7293

MSDS Number: BPVSG

=== Responsible Party ===

Company Name:ROCKWELL INTERNATIONAL CORP GOVERNMENT PRODUCTS

Address:2135 W MAPLE RD

City:TROY

State:MI

ZIP:48084-7121

Country:US

Preparer's Name:HMIS TECHNI

CIAN

CAGE:78500

=== Contractor Identification ===

Company Name:MERITOR HEAVY VEHICLE SYSTEMS LLC

Address:2135 W MAPLE RD

Box:City:TROY

State:MI

ZIP:48084

Country:US

Phone:248-435-8207

CAGE:78500

=====  
===== Composition/Information on Ingredients =====

Ingred Name:NON HAZARDOUS INGREDIENTS

Fraction by Wt: 100%

Other REC Limits:NONE RECOMMENDED

=====  
===== Hazards Identification =====

Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO

Reports of Carcin

ogenicity:NTP:NO IARC:NO OSHA:NO  
Health Hazards Acute and Chronic:NON HAZARDOUS  
Explanation of Carcinogenicity:NONE  
Effects of Overexposure:NON HAZARDOUS  
Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.

=====  
===== First Aid Measures =====

First Aid:INHALED: REMOVE PERSON TO FRESH AIR. EYES: FLUSH WITH WATER FOR 15 MINUTES. SEE DOCTOR. SKIN: WASH WITH SOAP AND WATER. INGESTED: CALL DOCTOR.

=====  
===== Fire Fighting Measures =====

Extinguishing Media:MEDIA APPROPRIATE FOR SURROUNDING FIRE.  
Fire Fighting Procedures:WEAR SELF-CONTAINED BREATHING APPARATUS AND PROTECTIVE CLOTHING.  
Unusual Fire/Explosion Hazard:NONE

=====  
===== Accidental Release Measures =====

Spill Release Procedures:SWEEP OR VACUUM UP DUST.  
Neutralizing Agent:NONE

=====  
===== Handling and Storage =====

Handling and Storage Precautions:KEEP DRY.  
Other Precautions:DO NOT GENERATE DUST. DO NOT USE AIR HOSE OR BRUSH TO REMOVE DUST AND FIBERS.

=====  
===== Exposure Controls/Personal Protection =====

Respiratory Protection:NONE NORMALLY REQUIRED.  
Ventilation:USE ADEQUATE MECHANICAL VENTILATION.  
Protective Gloves:COTTON, CANVAS  
Eye Protection:SAFETY GLASSES  
Other Protective Equipment:NONE  
Work Hygienic Practices:WASH HANDS AFTER USE AND BEFORE EATING, DRINKING, OR SMOKING.  
Supplemental Safety and Health  
MSDS GENERATED BY HMIS TECHNICIAN. MSDS NOT

REQUIRED BY 29 CFR. ITEM IS  
AN ARTICLE. MANUFACTURER CERTIFIED NO ASBESTOS.

===== Physical/Chemical Properties =====

HCC:N1  
Solubility in Water:NEGLIGIBLE  
Appearance and Odor:BRAKE SHOE FOR XM916, TRUCK, TRACTOR  
Percent Volatiles by Volume:0

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES  
NONE  
Stability Condition to Avoid:NONE  
Hazardous Decomposition Products:OXIDES OF CARBON

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND  
FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):  
This information is formulated for use by elements of the Department  
of Defense. The United States of America in no manner whatsoever,  
expressly or implied, warrants this information to be accurate and  
disclaims all liability for its use. Any person utilizing this  
document should seek competent professional advice to verify and  
assume responsibility for the suitability of this information to their  
particular situation.