

GE SILICONES -- RTV615B -- 8030-00-485-9200

===== Product Identification =====

Product ID:RTV615B

MSDS Date:04/11/1991

FSC:8030

NIIN:00-485-9200

Kit Part:Y

MSDS Number: BRKFL

==== Responsible Party ===

Company Name:GE SILICONES

Address:260 HUDSON RIVER ROAD

City:WATERFORD

State:NY

ZIP:12188

Country:US

Info Phone Num:518-237-3330

Emergency Phone Num:518-237-3330

Preparer's Name:DA POLSINELLI

CAGE:GE

SIL

==== Contractor Identification ===

Company Name:GE SILICONES

Address:260 HUDSON RIVER ROAD

City:WATERFORD

State:NY

ZIP:12188

Country:US

Phone:518-237-3330

CAGE:GESIL

Company Name:GENERAL ELECTRIC CO, SILICONE PRODUCTS BUSINESS DEPT

Address:260 HUDSON RIVER RD

Box:City:WATERFORD

State:NY

ZIP:12188

Country:US

Phone:518-237-3330/800-332-3390

CAGE:01139

===== Composition/Information on Ingredients =====

Ingred Name:TOLUENE (SARA III)

CAS:108-88-3

RTECS #:XS5250000

Fraction by

Wt: 500F,>260C

Extinguishing Media:ALL STANDARD FIREFIGHTING MEDIA

Fire Fighting Procedures:NONE KNOWN

===== Accidental Release Measures =====

Spill Release Procedures:WASH WALKING SURFACE WITH DETERGENT & WATER TO REDUCE SLIPPING HAZARD. WEAR PROPER PROTECTIVE EQUIPMENT AS SPECIFIED IN PROTECTIVE EQUIPMENT SECTION. WIPE, SCRAPE, OR SOAK UP IN INERT MATERIAL & PUT IN CONTAINER FOR FLAMMABLE MAT'L FOR DISPOSAL.

===== Handling and Storage =====

Handling and Storage Precautions:KEEP CONTAINER CLOSED WHEN NOT IN USE TO PREVENT CONTACT WITH ACIDIC, BASIC OR OXIDIZING MATERIALS AND METALLIC CATALYSTS LIKE TIN SOAP & NOBLE METALS

===== Exposure Controls/Personal Protection =====

Respiratory Protection:NONE KNOWN

Ventilation:NONE KNOWN

Protective Gloves:CLOTH GLOVES

Eye Protection:SAFETY GLASSES

Other Protective Equipment:NONE KNOWN

Supplemental Safety and Health

=====

Physical/Chemical Properties =====

HCC:N1

Boiling Pt:B.P. Text:>500F,>260C

Vapor Density:1.0

Spec Gravity:0.99 (WATER=1)

Solubility in Water:INSOLUBLE

Appearance and Odor:CLEAR LIQUID, SULFUR LIKE ODOR

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

AVOID CONTACT WITH ACIDIC, BASIC OR OXIDIZING AGENTS & METALLIC CATALYSTS LIKE TIN SOAPS & NOBLE METALS (PT, RH, ETC).

Stability Condition to Avoid:PRODUCT GENERATE

S FLAMMABLE GAS ON CONTACT

WITH ACIDS, BASES OR OXIDIZING MATERIALS.

Hazardous Decomposition Products:CARBON MONOXIDE, CARBON DIOXDE,

SILICON DIOXIDE, FLAMMABLE HYDROGEN GAS

Conditions to Avoid Polymerization:PRODUCT GENERATES FLAMMABLE GAS ON  
CONTACT WITH ACIDS, BASES OR OXIDIZING MATERIALS.

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSAL SHOULD BE MADE IN ACCORDANCE WITH

FEDERAL, STATE, AND LOCAL REGULATIONS. INCINERATION RE

COMMENDED IN

APPROVED INCINERATOR ACCORDING TO FEDERAL, STATE AND LOCAL  
REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department  
of Defense. The United States of America in no manner whatsoever,  
expressly or implied, warrants this information to be accurate and  
disclaims all liability for its use. Any person utilizing this  
document should seek competent professional advice to verify a  
nd

assume responsibility for the suitability of this information to their  
particular situation.