View NSN Online: https://aerobasegroup.ae/nsn/3439-00-015-5327

ALPHAMETALS INC. -- SOLDER OF ALLOYS OF LEAD, TIN, SILVER, BISMUTH -- 3439-00-015-5327

Product ID:SOLDER OF ALLOYS OF LEAD, TIN, SILVER, BISMUTH

MSDS Date:08/13/1987

FSC:3439

NIIN:00-015-5327

MSDS Number: BRNGN === Responsible Party ===

Company Name: ALPHAMETALS INC.

Address:600 RT 440 City:JERSEY CITY

State:NJ

ZIP:07304-1027 Country:US

Info Phone Num:201-434-6778

Emerg

ency Phone Num:201-434-6778

CAGE:96913

=== Contractor Identification === Company Name:DEANCO INC Address:7933 QUEENAIR DR Box:City:GAITHERSBURG

State:MD

ZIP:20879-4137

Country:US

Phone:301-948-5444

CAGE:9K946

Company Name: KINDEL R E AND CO

Address:326 E 3RD Box:City:CINCINNATI

State:OH

ZIP:45202-3510 Country:US CAGE:96913

====== Composition/Information on Ingredients ========

Ingred Name:LEAD (SARA III)

CAS:7439-92-1

RTECS #:OF7525000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:0

.05 MG/M3;1910.1025

ACGIH TLV:0.15 MG/M3;DUST 9293

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:TIN CAS:7440-31-5

RTECS #:XP7320000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:2 MG/M3

ACGIH TLV:2 MG/M3; 9293

Ingred Name: SILVER (SARA III)

CAS:7440-22-4

RTECS #:VW3500000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:0.01 MG/M3

ACGIH TLV:0.1 MG/M3; 9293

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:BISMUTH

CAS:7440-69-9

RTECS #:EB2600000

Other REC Limits: NONE RECOMMENDED

Ingred Name: ANTIMONY (SA

RA III)

CAS:7440-36-0

RTECS #:CC4025000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:0.5 MG/M3

ACGIH TLV:0.5 MG SB/M3; 9293

EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name: INDIUM

CAS:7440-74-6

RTECS #:NL1050000

Other REC Limits: NONE RECOMMENDED

OSHA PEL:0.1 MG/M3

ACGIH TLV:0.1 MG/M3; 9293

=========== Hazards Identification ==============

LD50 LC50 Mixture:TLV LEAD=0.05 MG/M3

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO

Reports of Carcinogenicity:NTP:NO IARC

:YES OSHA:NO Health Hazards Acute and Chronic:MOLTEN SOLDER DOES NOT PRODUCE SIGNIFICANT QUANTITIES OF FUME BELOW 900F.TIN:DUST/FUMES MAY IRRITATE SKIN AND MUCOUS MEMBRANES,POSSIBLE LUNG DAMAGE.SILVER:MAY DISCOLOR SKIN,EYES.BISMUTH:GUM DISCOLORAT ION/INFLAMATION.ANTIMONY:GI UPSET,INDIUM:MAY CAUSE BLOOD DAMAGE,LIVER AND KIDNEY DAMAGE.LEAD:LIVE AND CNS DAMAGE. Explanation of Carcinogenicity:LEAD COMPOUNDS ARE CONSIDERED TO BE A CANCER RISK BY IARC. Effects of Overexposure: ANTIMONY:SLEEPLESSNESS,IRITABILITY,MUSCLE
PAIN.INDIUM:WEIGHT LOSS.BISMUTH:BAD BREATH.SILVER:DISCOLORATION OF EYES AND SKIN.TIN:IRRITATION.LEAD:ANEMIA,INSOMNIA,WEAKNESS,CONSTIPATION,NAUS EA,ABDONIMAL PA IN.
Medical Cond Aggravated by Exposure:WOMEN OF CHILD BEARING AGE SHOULD AVOID CONTACT WITH LEAD.
======================================
First Aid:INHAL:REMOVE FROM EXPOSURE.CALL PHYSICIAN.INGEST:CALL PHYSICIAN OR POISON CONTROL CENTER.SKIN: HOT MEATL BURNS SHOULD BE COOLED WITH WATER;CALL PHYSICIAN.EYES:FLUSH WITH WATER;CAONTACT PHYSICIAN.
======================================
Flash Point:NONE Extinguishing Media:USE MEDIA APPROPRAITE FOR SURROUNDING FIRE. Fire Fighting Procedures:USE A SELF-CONTAINED BREATHING APPARATUS AND FULL PROTECTIVE CLOTHING. Unusual Fire/Explosion Hazard:THIS PRODUCT IN DUST FORM IS AN EXPLOSION HAZARD.LEAD FUMES ARE TOXIC.
======== Accidental Re lease Measures ==============
Tease Measures
Spill Release Procedures:AVOID INHALING FUMES OR DUST.VACUUMING IS RECOMMENDED.PLACE IN AN APPROPRIATE CONTAINER FOR DISPOSAL. Neutralizing Agent:NONE
======================================

Handling and Storage Precautions: DO NOT USE OR CONSUME FOOD, DRINK, TOBACCO OR COSMETICS IN WORK AREA.

Other Precautions:EMPTY PRODUCT CONTAINERS RETAIN RESIDUE AND MUST BE LABELED"FOR INDUSTRIAL USE ONLY.KEEP OUT OF REACH OF CHILDRE

N.DO NOT TAKE INTERNALLY". ===== Exposure Controls/Personal Protection ======== Respiratory Protection: USE A NIOSH APPROVED DUST/FUME RESPIRATOR WHEN TLV IS EXCEEDED. Ventilation: USE MECHANICAL (GENERAL) OR LOCAL EXHAUST. Protective Gloves: TO AVOID BURNS. Eye Protection: SAFETY OR WELDING GLASSES/HOOD. Other Protective Equipment: WORK CLOTHES SHOULD BE WORN. Work Hygienic Practices: WASH HANDS. SEPERATE WORK CLOTHES FROM STREET CLOTHES.LAUNDER WORK CLOTHES BEFORE REUSE.KE EP FOOD OUT OF THE WORK AREA. Supplemental Safety and Health NONE ======== Physical/Chemical Properties ============ HCC:N1 NRC/State Lic Num:NONE Solubility in Water: INSOLUBLE Appearance and Odor:METAL;SILVER-GRAY;ODORLESS ======== Stability and Reactivity Data =========== Stability Indicator/Materials to Avoid:YES OXIDIZING MATERIELS, ACIDS, HYDROGEN PEROXIDE. Stability Condition to Avoid: NONE Hazardous Decomposition Products: LEAD FUMES AND LEAD PARTICU LATES. ======= Disposal Considerations ============

Waste Disposal Methods: RECYLCLE OR DISPOSE OF IN ACCORDANCE WITH FEDERAL, STATE AND LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use.

Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.