Product ID:SYTLE 900 COMPRESSED ASBESTOS SHEETS MSDS Date:04/13/1987 FSC:5330 NIIN:01-375-4904 **MSDS Number: BSDCZ** === Responsible Party === Company Name: GARLOCK INC Address:1666 DIVISION ST City:PALMYRA State:NY ZIP:14522 Country:US Info Phone Num:315-597-4811 Emergency Phone Num:315-597-4811 Preparer's Name:H.R. HUGHES CAGE:76380 === Contractor Identification === **Company Name: GARLOCK INC** Address:1666 DIVISION ST Box:City:PALMYRA State:NY ZIP:14522 Country:US Phone:315-597-4811 CAGE:76380 Company Name: GARLOCK INC. Address:1666 DIVISION STREET Box:City:PALMYRA State:NY ZIP:14522-9355 Country:US Phone:315-597-4811 CAGE:6L329

Ingred Name:ASBESTOS, CHRYSOTILE CAS:12001-29-5 RTECS #:CI6478500 Fraction by Wt: 80-90% OS HA PEL:0.2 FIBERS, CC ACGIH TLV:2 FIBERS, CC

Ingred Name:SUPDAT:RESPONSIBLE FOR COMPLYING WITH ANY LOCAL, STATE AND FEDERAL REGULATIONS. RTECS #:9999999ZZ

Ingred Name:OTHER PREC:HEPA FILTERS SHOULD BE WORN BY INDIVIDUALS WHEN ENGAGED IN REMOVAL OF USED GASKETS. RTECS #:9999999ZZ

Ingred Name:VENT:SUFFICIENT VENT SHOULD BE PROVIDED TO KEEP FIBER LEVEL BELOW 0.2 FIBERS PER CC. RTECS #:99999992Z

LD50 LC50 Mixture:N

ONE SPECIFIED BY MANUFACTURER.

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO

Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:YES

Health Hazards Acute and Chronic:PRODUCTS DO NOT POSE HEALTH HAZARD UNDER ORDINARY CONDITIONS OF USE. A HAZARD WOULD ARISE ONLY IF PRODUCTS WERE SUBJECTED TO MECHANICAL ACTIONS THAT WOULD CAUSE THE ASBESTOS FIBERS TO BE RELEASED FROM THE ELASTOMER COMPOUND MATRIX. SKIN & EYES:SIMPLE IRRITATION IN SENSITIVE INDIVIDUALS. CHRONIC:INHAL

(EFTS OF OVEREXP)

Explanation of Carcinogenicity:ASBESTOS:IARC MONOGRAPHS, SUPPLEMENT,

VOL 7, PG 106, 1987:GROUP 1. NTP 6TH ANNUAL RPT ON CARCIN, 1991:KNOWN TO (SUPDAT)

Effects of Overexposure:HLTH HAZ:OF SUCH AIRBORNE FIBERS CAN CAUSE WELL-KNOWN LONG TERM EFFECTS OF ASBESTOSIS, LUNG CANCER & MESOTHELIOMA. INGEST:FREE ASBESTOS FIBERS MAY BE FACTOR IN CANCERS OF THE GI TRACT AND LARNYX. SUCH CANCERS ARE BELIEVED TO BE SMOKING RELATED.

Medical Cond Aggravated by Exposure:

NHALING FREE ASBESTOS FIBERS MAY

AGGRAVATE ANY LUNG CONDITIONS AND RESPIRATORY TRACT IRRITATIONS.

First Aid:INGEST: CALL MD IMMEDIATELY . INHAL: REMOVE VICTIM FROM CONTAMINATED AREA. REPORT EXPOSURE TO MEDICAL PERSONNEL. SKIN: WASH AREA OF CONTACT THOROUGHLY WITH SOAP AND WATER. CONTACT MD IF IRRITATI ON PERSISTS. EYES: IF PARTICLES GET IN THE EYES, IRRIGATE WELL WITH WATER FOR AT LEAST 15 MINUTES. CONTACT

MD AS A
PRECAUTION.

======================================
Extinguishing Media:WATER, FOAM, CARBON DIOXIDE, DRY CHEMICAL. Fire Fighting Procedures:USE NIOSH/MSHA APPROVED SCBA AND FULL PROTECTIVE EQUIPMENT.
Unusual Fire/Explosion Hazard:PRODUCES SMOKE, SOME FUMES AND POSSIBLY SOME FREE ASBESTOS FIBERS WHEN BURNED.
======================================
Spill Release Procedures:WET WASTE. VACUUM UP ANY WASTE WITH HEPA
FILTERED VACUUM CLEANER. WEAR PROTECTIVE EQUIPMENT AND HALF FACE RESPIRATOR WITH HEPA FILTERS. Neutralizing Agent:NONE SPECIFIED BY MANUFACTURER.
======================================
Handling and Storage Precautions:STORE IN CLEAN, DRY PLACE AWAY FROM STRONG OXIDIZING AGENTS. NORMAL WASH UP AFTER HANDLING IS RECOMMENDED.
Other Precautions: ASBESTOS BONDED BY ELASTOMER CMPD, HOWEVER, DO NOT MISUSE BY IMPROPER CUTTING/HNDLG. WHEN REMOVING USED GASK ETS, AVOID
EXCESSIVE MECH ACTIONS & PLACE ASBESTOS CONTAINING RESIDUES IN PLASTIC BAG FOR DI SP. AS PREC, HALF FACE RESP W/ (ING 3)
======================================
Respiratory Protection:NOT REQUIRED UNDER NORMAL CONDITIONS OF USE. IF ANY OPERATIONS ARE PERFORMED ON PRODUCT THAT MAY RELEASE ASBESTOS FIBERS, USE A NIOSH/MSHA APPROVED HALF FACE RESPIRATOR WITH HEPA FILTERS.
Ventilation:NO SPECIAL REQUIREMENT UNDER NORM CNDTNS. IF ANY OPERAT IONS
PERFORMED ON PROD THAT MAY RELS ASBESTOS FIBERS, (ING 4) Protective Gloves: IMPERVIOUS GLOVES .
Eye Protection:ANSI APPROVED SAFETY GLASSES . Other Protective Equipment:NOT REQUIRED UNDER ORDINARY CONDITIONS OF USE.
Work Hygienic Practices:NORMAL WASH UP AFTER HANDLING IS RECOMMENDED. Supplemental Safety and Health HAZ DECOMP PROD:MAY BE OTHER PRODS UNKNOWN TO MFR. EXPLAN OF CARCIN:BE CARCIN. CODE OF FED REGS, VOL 29, PG 1910.1001, 1987:OSHA CANCER HAZ. WASTE DISP METH:SUCH D

UST SHOULD BE WETTED & VACUUMED UP W/	
HEPA FILTERED VACUUM CLEANER, SEALED INPLASTIC BAG & DISP I/A/W	
INSTRUCTIONS FROM DISP COMPANY. USER IS (ING 2)	

HCC:T7 Solubility in Water:NEGLIGIBLE Appearance and Odor: OFF-WHITE SHEET OR GASKETS; SLIGHT ODOR. Stability Indicator/Materials to Avoid:YES AVOID STORAGE WITH STRONG OXIDIZING AGENTS. DIRECT FLAME WI LL IGNITE BINDER. Stability Condition to Avoid:STABLE UNDER NORMAL CONDITIONS OF STORAGE AND USE. Hazardous Decomposition Products: IN FIRE: SMOKE, POSS CO UNDER CERTAIN CIRCUMSTANCES. SOME ASBESTOS FIBERS MAY BE RELS ONCE BINDER HAS BURNED. (SUPDAT) Waste Disposal Methods: SINCE ASBESTOS IN PROD IS SECURED W/BINDER & IS NOT FRIABLE OR LOOSE, PROD CAN BE DISPOSED OF W/OTHER INERT MATLS IN NORM LANDFILL. GR INDING/MACHINING OF PROD SHOULD BE AVOIDED SINCE THESE/SIMILAR OPE RATIONS MAY GENERATE ASBESTOS DUST. ANY(SUPDAT) Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department

of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent p rofessional advice to verify and assume responsibility for the suitability of this information to their particular situation.