View NSN Online: https://aerobasegroup.ae/nsn/3439-01-045-9145

UNITED STATES WELDING CORP. -- TITANIUM WELD WIRE -- 3439-01-045-9145

Product ID:TITANIUM WELD WIRE MSDS Date:01/06/1987 FSC:3439 NIIN:01-045-9145 MSDS Number: BSTYJ === Responsible Party === Company Name: UNITED STATES WELDING CORP. Address:20700 DEARBORN STREET City:CHATSWORTH State:CA ZIP:91311 Country:US Info Phone Num:818-341-2021 Emergency Phone Num:818-341-2021 Preparer's Name: JORGE JACOBS CAGE:3H796 === Contractor Identification === Company Name: UNITED STATES WELDING CORP. Address:20700 DEARBORN STREET Box:City:CHATSWORTH State:CA ZIP:91311 Country:US Phone:818-341-2021 CAGE:3H796 Ingred Name: TITANIUM, METAL CAS:7440-32-6 RTECS #:XR1700000

Fraction by Wt: 99% Other REC Limits:NONE RECOMMENDED

Routes of Entr

y: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:INHAL:FUMES MAY CAUSE IRITATION.CHRONIC EXPOSURE MAY CAUSE NEUROLOGICAL OR LUNG DAMAGE.SKIN:NO HAZARD LIKELY.EYES:NO HAZARD LIKELY.INGEST:NO HAZARD LIKELY.
Explanation of Carcinogenicity:THERE ARE NO INGREDIENTS ABOVE 0.1% WHICH ARE IDENTIFIED AS CARCINOGENS BY NTP,IARC OR OSHA. Effects of Overexposure:INHAL:DIZZINESS,NAUSEA,DRYNESS OR IRRITATION OF T
HE NOSE AND THROAT, WATERY EYES, DIFFICULT BREATHING, COUGHING, CHEST PAIN.
Medical Cond Aggravated by Exposure:PERSONS WITH PRE-EXISTING RESPIRATORY AILMENTS MAY BE AT INCREASED RISK FROM EXPOSURE.
======================================
First Aid:SKIN:REMOVE CONTAMINATED CLOTHING;WASH WITH WATER.EYES:FLUSH WITH WATER FOR 15 MINUTES.INHAL:REMOVE TO FRESH AIR.GIVE OXYGEN OR ARTIFICIAL RESPIRATION IF NEEDED.INGEST:DO NOT INDUCE VOMITING.GET PROMP T Q
UALIFIED MEDICAL ATTENTION.
======================================
Flash Point:NONE Extinguishing Media:DRY CHEMICAL. Fire Fighting Procedures:USE A SELF-CONTAINED BREATHING APPARATUS AND FULL PROTECTIVE EQUIPMENT. Unusual Fire/Explosion Hazard:MOLTEN METAL MY EXPLODE ON CONTACT WITH WATER.
======================================
Spill Release Procedures:SWEEP UP.PLACE IN AN APPROPRIATE CONTAINER FOR DISPOSAL. Neutralizing Agent:NONE
======================================
Handling and Storage Precautions:NO SPECIAL REQUIREMENTS. Other Precautions:NONE
======================================
Respiratory Protection:USE A NIOSH APPROVED RESPIRATOR FOR METAL FUMES. Ventilation:LOCAL VENTILATION AT THE WORKSITE;MECHANICAL(GENERAL) VENTILATION TO MAINTAIN TLV/PEL. Protective Gloves:WELDING GLOVES Eye Protection:SAFETY GLASSES-WELDING HELMET Other Protecti

HCC:N1 Solubility in Water:INSOLUBLE

Appearance and Odor:WELDING ROD, 0.093 DIAMETER, 36 INCHES LONG.

Stability Indicator/Materials to Avoid:YES RUST,METAL OXIDES(EG.OXIDE OF COPPER,IRON AND LEAD). Stability Condition to Avoid:NONE Hazardous Decomposition Products:METAL FUMES.

Waste Disposal Methods:DISPOSE OF OR RECOVER IN ACCORDANCE WITH FEDERAL,STATE AND LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly

or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.