

CHRYSLER CORP SERVICE AND PARTS OPERATIONS -- MOPAR SILICONE RUBBER ADHESIVE SEALANT -- 5330-01-165-2363

=====
Product Identification
=====

Product ID:MOPAR SILICONE RUBBER ADHESIVE SEALANT
MSDS Date:10/31/1990
FSC:5330
NIIN:01-165-2363
MSDS Number: BTVRW
=== Responsible Party ===
Company Name:CHRYSLER CORP SERVICE AND PARTS OPERATIONS
Address:26311 LAWRENCE AVE
City:CENTER LINE
State:MI
ZIP:4801
5-9960
Country:US
Info Phone Num:313-252-5603/313-497-0815
Emergency Phone Num:313-956-5478/313-956-5557
CAGE:86403
=== Contractor Identification ===
Company Name:CHRYSLER CORP SERVICE AND PARTS OPERATIONS
Address:26311 LAWRENCE AVE
Box:City:CENTER LINE
State:MI
ZIP:48015-9960
Country:US
Phone:313-956-5478/313-956-5557
CAGE:86403

=====
Composition/Information on Ingredients
=====

Ingred Name:METHYLTRACETOXYSILANE, ALKYL TRIACETOXY SILANE
CAS:4253-34-3
RTECS #:VV4500000
Fract
ion by Wt: 1-5%

Ingred Name:ACETIC ACID (GLACIAL)
CAS:64-19-7
RTECS #:AF1225000
Fraction by Wt: 5-10%
OSHA PEL:10 MG/CUM
ACGIH TLV:10 MG/CUM
EPA Rpt Qty:5000 LBS
DOT Rpt Qty:5000 LBS

Ingred Name:SILICON DIOXIDE, CELITE 322
CAS:7631-86-9
RTECS #:VV3100000
Fraction by Wt: 10-30%
OSHA PEL:6 MG/CUM
ACGIH TLV:0.2 MG/CUM

=====
Hazards Identification
=====

Routes of Entry: Inhalation:YES Skin:NO Ingestion:YES

Health Hazards Acute and Chronic:HAZARDS FOR UNCURED PRODUCT.

INGESTION: MAY BE HARMFUL, MUCOUS MEMBRANE IRRITATION. SKIN/EYES: MAY PRODUCE IRRITATION. INHALATION: IRRITATION OF UPPER RESPIRATORY TRACT.

Explanation of Carcinogenicity:NONE

Effects of Overexposure:HAZARDS ARE FOR UNCURED PRODUCT. INGESTION: MAY BE HARMFUL, MUCOUS MEMBRANE IRRITATION. SKIN/EYES: MAY PRODUCE IRRITATION. INHALATION: MAY PRODUCE IRRITATION OF UPPER RESPIRATORY TRACT.

=====
First Aid Measures =====

First Aid:INGESTION: RINSE MOUTH W/WATER. EYES: RINSE IMMEDIATELY W/PLENTY OF WATER, LIFTING BOTH UPPER & LOWER LIDS, CONTINUE FOR 15 MINS. SKIN: WIPE OFF W/A CLOTH. WASH W/SOAP & WATER. INHALATION: REMOVE TO FRESH AIR AT ONCE. OBTAIN MEDICAL ATTENTION IN ALL CASES.

=====
Fire Fighting Measures =====

Extinguishing Media:WATER FOG, FOAM, ABC EXTINGUISHER, CO2/HALON
Fire Fighting Procedures:USE WATER TO COOL FIRE EXPOSED CONTAINERS. USE SCBA FOR ENCLOSED AREAS.

=====
Accidental Release Measures =====

Spill Release Procedures:WIPE/SCRAPE UP RESIDUE. ABSORB ON AN INERT MATERIAL. SHOVEL INTO STORAGE CONTAINERS. WASH AREA W/DETERGENT & WATER.

=====
Handling and Storage =====

Handling and Storage Precautions:KEEP CONTAINER TIGHTLY CLOSED WHEN NOT IN USE. AVOID PROLONGED/REPEATED SKIN CONTACT. AVOID EYE CONTACT.

Other Precautions:WEARERS OF CONTACT LENSES MUST NOT HANDLE LENS UNTIL ALL OF THE PRODUCT HAS BEEN CLEANED FROM FINGERTIPS. RESIDUAL SILICONE WILL CAUSE SEVERE EYE IRRITATION.

=====
Exposure Controls/Personal Protection =====

Respiratory Protection:ACID GAS RESPIRATOR MAY BE REQUIRED DURING CURE.

Ventilation:LOCAL EXHAUST. DEPENDING ON PROCESS GOOD GENERAL

Protective Gloves:COTTON

Eye Protection:SAFETY GLASSES W/SIDE SHIELDS

Other Protective Equipment:EYE WASH

Work Hygiene

ic Practices:WASH THOROUGHLY AFTER HANDLING. MAINTAIN GOOD
HOUSEKEEPING & HYGIENIC PRACTICES.

Supplemental Safety and Health

===== Physical/Chemical Properties =====

HCC:N1

Spec Gravity:1.02

Solubility in Water: