View NSN Online: https://aerobasegroup.ae/nsn/3439-00-165-4182

Product ID:STELLITE 1, 4, 6, TP-6, 12, 21, 25, 31, 190, 694 MSDS Date:04/16/1992 FSC:3439 NIIN:00-165-4182 MSDS Number: BVGHJ === Responsible Party === Company Name:STOODY CO Address:5557 NASHVILLE RD Box:9997 **City:BOWLING GREEN** State:KY ZIP:42102-4997 Country:US Info Phone Num:502-781-9777 Emergency Phone Num:502-781-9777 Preparer's Name:UNKNOWN. CAGE:57965 === Contractor Identification === Company Name:STOODY CO Box:90032 **City:BOWLING GREEN** State:KY ZIP:42102-9032 Country:US Phone:502-781-9777 CAGE:57965

Ingred Name:MANGANESE (SARA III) CAS:7439-96-5 RTECS #:OO9275000 Fraction by Wt: 0 - 2% Other REC Limits:NONE RECOMMENDED OSHA PEL:C 5 MG/M3 DUST ACGIH TLV:5 MG/M3 DUST 9394

Ingred Name:SILICON CAS:

7440-21-3 RTECS #:VW0400000 Fraction by Wt: 0 - 5% Other REC Limits:NONE RECOMMENDED OSHA PEL:15 MG/M3 TDUST ACGIH TLV:10 MG/M3 TDUST; 9394

Ingred Name:CHROMIUM (SARA III) CAS:7440-47-3 RTECS #:GB4200000 Fraction by Wt: 20 - 40% Other REC Limits:NONE RECOMMENDED OSHA PEL:1 MG/M3 ACGIH TLV:0.5 MG/M3; 9394 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:NICKEL (SARA III) CAS:7440-02-0 RTECS #:QR5950000 Fraction by Wt: 0 - 5% Other REC Limits:NONE RECOMMENDED OSHA PEL:1 MG/M3 ACGIH TLV:1 MG/M3; 9 394

Ingred Name:MOLYBDENUM (INSOLUBLE COMPOUNDS) CAS:7439-98-7 RTECS #:QA4680000 Fraction by Wt: 0 - 10% Other REC Limits:NONE RECOMMENDED OSHA PEL:15 MG/M3 TDUST ACGIH TLV:10 MG/M3; 9394

Ingred Name:IRON CAS:7439-89-6 RTECS #:NO4565500 Fraction by Wt: 0 - 5% Other REC Limits:NONE RECOMMENDED

Ingred Name:TUNGSTEN,AS W,SOLUBLE COMPOUNDS. CAS:7440-33-7 RTECS #:YO7175000 Fraction by Wt: 0 - 15% Other REC Limits:NONE RECOMMENDED OSHA PEL:NONE ESTABLISHED ACGIH TLV:1 MG/M3/3 STEL;9394

Ingred Name

:COBALT (SARA III),DUST AND FUME CAS:7440-48-4 RTECS #:GF8750000 Fraction by Wt: 30 - 60% Other REC Limits:NONE RECOMMENDED OSHA PEL:0.1 MG/M3 ACGIH TLV:0.05 MG/M3;DUST 9394

LD50 LC50 Mixture: UNKNOWN. Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:NO Health Hazards Acute and Chronic: TARGET ORGANS: LUNGS, CNS, EYES, SKIN. ACUTE- OVEREXPOSURE TO WELDING FUMES MAY CAUSE DISCOMFORT, LUNG DAMAGE, DRYNESS/IRRITATION OF NOSE, THROAT & EYES, TIGHTNESS IN CHEST, FEVER, METALLIC TASTE & ALL ERGIC REACTIONS. SPARKS & UV LIGHT CAN INJURE EYES & BURN SKIN. CHRONIC- LUNG & LIVER DAMGE, ALLERGIC SKIN RECTIONS. Explanation of Carcinogenicity: CONTAINS CHROMIUM AND NICKEL. Effects of Overexposure: EYES, NOSE AND THROAT IRRITATION OR DRYNESS, DIZZINESS, WATERY EYES, HEADACHE, NAUSEA, BREATHING DIFFICULTY, FREQUENT COUGHING, CHEST PAINS, ASTHMA-LIK E SYMTOMS, TIGHTNESS IN CHEST, FEVER, ALLERGIC SK IN RASHES, METALLIC TASTE Medical Cond Aggravated by Exposure: PERSONS WITH IMPAIRED PULMONARY FUNCTION, AIRWAY DISEASES AND CONDITIONS SUCH AS ASTHMA, EMPHYSEMA, CHRONIC BRONCHITIS. ETC... CAN BE AGGRAVATED BY THE EXPOSURE TO

First Aid:OBTAIN MEDICAL ATTENTION. EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY THE AMERICAN RED CROSS.

METAL FUMES.

Flash Point:NOT RELEVANT

Extinguishing Media:NON-FLAMMABLE. WELDING ARC AND SPARKS CAN IGNITE COMBUSTIBLES AND FLAMMABLES.

Fire Fighting Procedures: MAY FORM TOXIC GASES WHILE WELDING. WEAR PROTECTIVE CLOTHING AND NIOSH-APPROVED SELF-CONTAINED BREATHING APPARATUS OPERATED IN POSITIVE PRESSURE MODE.

Unusual Fire/Explosion Hazard:REFER TO AMERICAN NATIONAL STANDARD Z49.1 FOR FIRE PREVENTION DURING THE USE OF WELDING AND ALLIED

PROCEDURES.

Spill Release Procedures:NOT RELEVANT Neutralizing Agent:NOT RELEVANT

Handling and Storage Precautions:STORE IN A DRY PLACE AWAY FROM ACIDS. Other Precautions:CAUTION! INFRARED RADIATION FROM FLAMES CAN INJURE EYES. NOISE CAN DAMGE HEARING. ELECTRICAL SHOCK CAN KILL. MAY FORM TOXIC FUMES WHILE WELDING. AVOID BREATHING FUMES. USE WITH AD EQUATE

VENTILATION. W ASH THOROUGHLY AFTER HANDLING.

Respiratory Protection: USE NIOSH APPROVED SUPPLIED AIR RESPIRATORY PROTECTION OR RESPIRABLE FUME RESPIRATOR WHEN WELDING, BRAZING OR SOLDERING IN CONFINED SPACE OR WHERE LOCAL EXHAUST OR VENTILATION DOES NOT KEEP EXPOSURE B ELOW TLV.

Ventilation:LOCAL EXHAUST VENTILATION SHOULD BE USED TO CONTROL EXPOSURE TO AIRBORNE FUMES WHENEVER POSSIBLE.

Protective GI

oves:FLAME-PROOF WELDING GLOVES

Eye Protection: SAFETY GLASSES UNDER WELDING HELMET

Other Protective Equipment: EYE WASH STATION, SAFETY SHOWER, WORK CLOTHING AND APRON FOR WELDING.

Work Hygienic Practices:OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND RECOMMENDED PROCEDURES. TRAIN WELDERS NOT TO TOUCH LIVE ELCTRICAL PARTS.

Supplemental Safety and Health

FORMULA CHANGED. FOR PREVIOUS FORMULATIONS, SEE PNI A OR B OR C, SAME NSN.

HCC:T6

NRC/State Lic Num:NOT RELEVANT Viscosity:NOT RELEVANT Evaporation Rate & amp; Reference:NOT RELEVANT Solubility in Water:INSOLUBLE Appearance and Odor:WELDING ROD

Stability Indicator/Materials to Avoid:YES STRONG ACIDS Stability Condition to Avoid:UNKNOWN. Hazardous Decomposition Products:PRIMARILY COMPLEX OXIDES OF COBALT, CHROMIUM AND NICKEL; SECONDARILY COMPLEX OXIDES OF MN, SI, FE, BORON, MO, TU

NGSTEN

Waste Disposal Methods:PRIOR TO DISPOSAL, CONSIDER IF MATERIAL HAS RECOVERY VALUE. DISPOSE OF IN ACCORDANCE WITH ALL LOCAL, STATE AND FEDERAL REGULATIONS. PREVENT WASTE FROM CONTAMINATING ENVIRONMENT.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, ex

pressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.