Product ID:ZIRMET METSPLICE BELTS, 16-5400-060-005 MSDS Date:03/21/1990 FSC:5345 NIIN:01-167-4893 **MSDS Number: BWFPN** === Responsible Party === Company Name: BUEHLER LTD Address:41 WAUKEGAN RD City:LAKE BLUFF State:IL ZIP:60044 Country:US Info Phone Num:708-295-6500 Emergency Phone Num:708-295 -6500 Preparer's Name: THOMAS R. DERAM CAGE:09410 === Contractor Identification === Company Name: BUEHLER LTD. Address:41 WAUKEGAN RD. Box:City:LAKE BLUFF State:IL ZIP:60044-1687 Country:US Phone:847-295-8500 CAGE:09410 Ingred Name: ALUMINUM OXIDE CAS:1344-28-1 RTECS #:BD1200000 Fraction by Wt: 60%

Other REC Limits:NONE RECOMMENDED OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST

Ingred Name:ZIRCONIUM OXIDE CAS:1314-23-4 RTECS #:ZH8800000 Fraction by Wt: 40% Other REC Limits:NONE RECOMMENDED OSHA PEL:5 MG/M3 AS ZR ACGIH TLV:5 MG/M3 AS ZR

LD50 LC50 Mixture:LD50 (ORAL RAT) IS UNKNOWN. Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic: TARGET ORGANS: EYES, SKIN, RESPIRATORY TRACT. ACUTE- MAY CAUSE SKIN ABRASIONS. INHALATION OF DUSTS MAY CAUSE COUGHING, SHO RTNESS OF BREATH. NO KNOWN ADVERSE EFFECTS BY INGESTION, BUT INGESTION NOT RECO MMENDED. MAY CAUSE EYE IRRITATION. CHRONIC- DUST MAY AFFECT BREATHING CAPACITY. Explanation of Carcinogenicity:NONE Effects of Overexposure: EYES AND SKIN IRRITATION; COUGHING, SHORTNESS OF BREATH First Aid:GET MEDICAL HELP IF SYMPTOMS PERSIST. INHALED:REMOVE TO FRESH AIR. PROVIDE CPR/OXYGEN IF NEEDED. EYES:FLUSH WITH WATER FOR 15 MINUTES, HOLDING EYELIDS OPEN. SKIN: WASH WITH SOAP & WATER. ORAL:GET MEDIC AL ATTENTION IF NEEDED. Flash Point:NONE Extinguishing Media:WATER SPRAY, CARBON DIOXIDE, FOAM OR DRY CHEMICAL FOR SURROUNDING FIRE. USE WATER SPRAY TO COOL FIRE EXPOSED CONTAINERS. Fire Fighting Procedures: AS WITH ANY FIRE, WEAR PROTECTIVE CLOTHING AND NIOSH-APPROVED SELF-CONTAINED BREATHING APPARATUS TO AVOID INHALATION OF HAZA RDOUS DECOMPOSTION PRODUCTS.

Spill Release Procedures:NORMAL CLEANUP PROCEDURES. DO NOT RAISE DUST. DO NOT BREATHE DUST. Neutralizing Agent:NOT RELEVANT

Handling and Storage Precautions:STORE AND HANDLE WITH ADEQUATE VENTILATION. A FORMALDEHYDE OR PHENOLIC RESIN ODOR MAY BE ON OCCASION BE RELEASED DURING STORAGE. Other Precautions:DO NOT RAISE DU ST. AVOID CONTACT WITH EYES, SKIN OR CLOTHING. AVOID INHALATION OF DUST. WASH THOROUGHLY AFTER HANDLING MATERIAL. KEEP OUT OF REACH OF SMALL CHILDREN.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection: NONE NORMALLY REQUIRED. IF AIRBORNE CONCENTRATION IS HIGH, WEAR A NIOSH-APPROVED DUST RESPIRATOR OR DUST MASK (OSHA 29 CFR 1910.134). Ventilation:LOCAL AND/OR MECHANICAL RECOMMENDED Protective Gloves: RUBBER AS DESIRED BY USER **Eve Protection** :SAFETY GOGGLES RECOMMENDED Other Protective Equipment: EYE WASH STATION, SAFETY SHOWER, PROTECTIVE **CLOTHING AND/OR UNIFORM** Work Hygienic Practices: OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND **RECOMMENDED PROCEDURES.** Supplemental Safety and Health HCC:T6 NRC/State Lic Num:NOT RELEVANT Evaporation Rate & amp; Reference: NOT RELEVANT Solubility in Water: UNKNOWNE Appearance and Odor: CLOTH COATED WITH ABRASIVE MATERIAL

Stability Indicator/Materials to Avoid:YES Hazardous Decomposition Products:FUMES MAY BE GENERATED.

Waste Disposal Methods:STANDARD LANDFILL METHODS CONSISTENT WITH APPLICABLE LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of D efense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.