View NSN Online: https://aerobasegroup.ae/nsn/3439-01-382-1225

Product ID:METCO 72F-NS MSDS Date:08/29/1994 FSC:3439 NIIN:01-382-1225 MSDS Number: BXPWQ === Responsible Party === Company Name: METCO INC, SUB OF THE PERKIN-ELMER CORP Address:1101 PROSPECT AVENUE Box:1006 City:WESTBURY State:NY ZIP:11590-0201 Country:US Info Phone Num:516-334-1300 Emerg ency Phone Num:800-424-9300(CHEMTREC) CAGE:39918 === Contractor Identification === Company Name: METCO INC, SUB OF THE PERKIN-ELMER CORP Address:1101 PROSPECT AVENUE Box:City:WESTBURY State:NY ZIP:11590-2724 Country:US Phone:516-334-1300 CAGE:39918 Ingred Name: TUNGSTEN CARBIDE

CAS:12070-12-1 RTECS #:YO7250000 Fraction by Wt: 87% Other REC Limits:NONE RECOMMENDED OSHA PEL:5 MG W/M3 ACGIH TLV:5 MG W/M3

Ingred Name:COBALT (SARA

313) CAS:7440-48-4 RTECS #:GF8750000 Fraction by Wt: 12% Other REC Limits:NONE RECOMMENDED OSHA PEL:0.1 MG/M3 ACGIH TLV:0.02 MG/M3; A3; 9495

Ingred Name:IRON CAS:7439-89-6 RTECS #:NO4565500 Fraction by Wt: 1% Other REC Limits:NONE RECOMMENDED

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:TUNGSTEN CARBIDE:INHAL/SKIN/EYE HAZ.MAY CAUSE LUNG DMG & RESP TRACT/EYE/SKIN IRRIT. COBALT:SKIN/INHAL HAZ.MAY CAUSE PROGRESSIVE, DIFFUSE PNEU, RESP SENS, ALLERGIC DERM/ECZEMA. IRON: INHAL HAZ. MAY CAUSE SI DEROSIS(BENIGN PNEUMOCONIOSIS). INGEST: POSSIBLE IRRITATION. Explanation of Carcinogenicity: PER MSDS: COBALT FOUND TO BE CONFIRMED CARCINOGEN BY OTHER REF GUIDE SOURCES SUCH AS CARC ACTIVE CHEM FRM VAN NOSTRAND. Effects of Overexposure: LUNG DAMAGE, RESP TRACT/EYE/SKIN IRRITATION. PROGRESSIVE, DIFFUSE PNEUMONIA, RES P SENSITIZATION CHARACTERIZED BY COUGH, WHEEZING & SHORTNESS OF BREATH. ALLERGIC DERMATITIS OR ECZEMA. SIDEROSIS (BENIGN PNEUMOCONIOSIS). Medical Cond Aggravated by Exposure: CONSULT A PHYSICIAN. TARGET

ORGANS:TUNGSTEN CARBIDE:LUNGS,SKIN,EYE; COBALT:LUNGS,SKIN; IRON:LUNGS.

First Aid:EYE:FLUSH W/WATER FOR @LEAST 15-20MINS OPENING EYELIDS. IRRIT PERSISTS CONSULT PHYSICIAN. SKIN:WASH W/SOAP/WATER. INHAL:EXPO ΤО

FRESH AIR. CONSULT PHYSICIAN IF IRRIT/RESP DISTRESS PERSISTS. INGEST:CON SULT PHYSICIAN.

Extinguishing Media:USE CLASS D FIRE EXTINGUISHER. Fire Fighting Procedures:TREAT AS METALLIC FIRE. USE NIOSH/MSAH APPROVED SELF-CONTAINED BREATHING APPARATUS & FULL PROTECTIVE CLOTHING IF INVOLVED IN FIRE. Unusual Fire/Explosion Hazard:FINE METAL DUSTS FLAMM;MAY EXPLO WHEN EXPO TO HEAT/FLAME/STRONG OXIDIZERS.TUNGST EN CARBIDE OXIDIZES ON

HEATING IN AIR; BURNS IN FLUORINE @RT.COBALT MAY IGN (SUP)

Spill Release Procedures: VACUUM LOOSE POWDER ONLY W/VACUUMS EQUIPPED W/HEPA FILTRATION. VACUUMS APPROPRIATE FOR USE W/METALLIC DUSTS SHOULD BE UTILIZED. WIPE AREA CLEAN. DO NOT USE WATER FOR CLEAN UP OPERATIONS. DO NOT SWEEP. AVOID GENERATING AIRBORNE DUST. Neutralizing Agent: NONE SPECIFIED BY MANUFACTURER.

\_\_\_\_\_

Handling and Storage Precautions:STORE AWAY FRM INCOMPATIBLES.STORE CNTNRS IN WELL-VENTILATED CLEAN COOL DRY AREA.STORE IN MANNER TO MIN PUNCTURES & BREAKAGE OF CNTNRS.

Other Precautions:AVOID INGEST/INHAL/EXCESSIVE SKIN CONTACT. AVOID CONTACT OF POWDER W/WATER & OXIDIZERS. GOGG:LENS SHADES:COMBUST SPRAY SHADE #5,PLASMA SPRAY UP TO 40KW SHADE #9,40-60KW SHADE #10,>60KW SHADE #11.

======= Exposure Controls/Personal Protect

ion =============

Respiratory Protection: A RESPIRATOR APPROVED BY NIOSH W/FILTER CARTRIDGES APPROVED FUR DUST/FUMES/MISTS SHOULD BE WORN @ALL TIMES DURING THERMAL SPRAY PROCESS TO PROTECT OPERATOR FRM EXPO TO DUST/FUMES.RESP MAY ALSO BE WORN WHEN PROD HNDLG GENERATES DUST.
Ventilation: PRODUCT SHOULD BE USED WITH APPROPRIATE LOCAL EXHAUST VENTILATION PROVIDED.
Protective Gloves: ALUMINIZED-PLASMA SPRAY; RUBB-OTHER.
Eye Protection: GOGGLES. (SEE OTHER PRECAUTIONS) Other Protective Equipment:EAR PROT FOR EXCESS NOISE LEVEL.ALUMINIZED APRON FOR PLASMA SPRAY.OTHER APPRO PROT CLOTH AS NECESSARY.EYEWASH.WASH FACIL Work Hygienic Practices:WASH WELL AFTER HANDLING. Supplemental Safety and Health FIRE/EXPLO HAZ:IF AIRBORNE IN PRESENCE OF IGN SOURCE/SPONTANEOUSLY.IRON MAY IGN IF AIRBORNE IN PRESENCE OF IGN SOURCE.

HCC:N1 Melt/Freeze Pt:M.P/F.P Text:2200F,1204C Spec Gravity:4.5-6.3 Appearance and Odo r:POWDER, NO ODOR.

Stability Indicator/Materials to Avoid:YES
OXIDIZERS, ACIDS, SULFUR, NI(NO3)2, COMBUSTIBLES.
Stability Condition to Avoid:AVOID ALL SOURCES OF IGNITION, DUST GENERATION, & WATER.
Hazardous Decomposition Products:OZONE & NITRIC OXIDE ARE FORM BY PLASMA FLAME(SIMILAR TO WELDING FUMES).THIS ACTION IS INDEPENDENT OF METAL POWDER.

W

aste Disposal Methods:EMPTY PROD CNTNRS,PROD WASTE,& CLEANING MEDIA SHOULD BE STORED & DISPOSED OF ACCORDING TO APPROPRIATE LOCAL, STATE AND FEDERAL REGULATORY GUIDELINES. CONTAINS COBALT:SUB TO REPORTING RQMTS OF SARA SE C313 & ON HAZ AIR POLLUTANTS EPA CLEAN AIR ACT.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, e

xpressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.