Address:829 PARKVIEW BOULEVARD

City:LOMBARD

State:IL

ZIP:60148-324

a

Country:US

Info Phone Num:708-629-5200

Emergency Phone Num:708-629-5200

CAGE:88219

=== Contractor Identification ===

Company Name: EXIDE TECHNOLOGIES INC CO, GNB INDUSTRIAL POWER DIV

Address:829 PARKVIEW BOULEVARD

Box:City:LOMBARD

State:IL

ZIP:60148-3249 Country:US

Phone:800-872-0471/630-691-7841

CAGE:88219

======= Composition/Information on Ingredients ========

Ingred Name:LEAD (SARA 313) (CERCLA)

CAS:7439-92-1

RTECS #:OF7525000 Fraction by Wt: 50%

Other REC Limits: NONE RECOMMEN

**DED** 

OSHA PEL:SEE 1910.1025

ACGIH TLV:0.15MG/M3 DUST; 9495

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name: SULFURIC ACID (SARA 302/313) (CERCLA)

CAS:7664-93-9

RTECS #:WS5600000 Fraction by Wt: 27%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:1 MG/M3

ACGIH TLV:1 MG/M3/3 STEL; 9495

EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

========== Hazards Identification ===============

LD50 LC50 Mixture:PRODUCT'S LD50 (ORAL RAT) WAS NOT STATED

Routes of Entry: Inhalation: NO Skin: YES Ingestion:

YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic: EYE & SKIN IRRITATION. **Explanation of Carcinogenicity:NONE** Effects of Overexposure: STINGING & BURNING SENSATION TO SKIN & EYES. Medical Cond Aggravated by Exposure: EXPOSURE TO ACID MIST CAN AGGRAVATE PULMONARY CONDITIONS. First Aid:SKIN-FLUSH THOROUGHLY W/WATER. EYES-FLUSH IMMEDIATELY W/WATER & GET PROMPT MEDICAL ATTENTION, CONTI NUE FLUSHING EYES FOR AT LEAST 15 MIN OR UNTIL MEDICAL ATTENTION. Lower Limits:N/A. Upper Limits:N/A. Extinguishing Media: DRY CHEMICAL. Fire Fighting Procedures:ORDINARY. Unusual Fire/Explosion Hazard: WHEN ON CHARGE AND APPROACHING FULL CHARGE, GASES GENERATED ARE VOLITILE. KEEP SOURCES OF IGNITION (SPARKS AND FLAMES) AWAY. ======== Accidental Release Measures ============ Spill Release Procedu res:APPLY AN EQUAL AMOUNT OF BAKING SODA, SODA ASH, CAUSTIC SODA OR EQUIVALENT OVER SPILLED ELECTROLYTE TO NEUTRALIZE IT & DD WATER IF NECESSARY TO FORM A SLURRY. SCOOP UP SLURRY. Neutralizing Agent: BAKING SODA, SODA ASH, CAUSTIC SODA. ============= Handling and Storage ========================== Handling and Storage Precautions: STORE WITH VENT SIDE UP. BE CERTAIN VENTS ARE FREE OF DIRT ETC. TO INSURE AIR FLOW. Other Precautions: DO NOT SHORT OUT POSITIVE & NEGATIVE ELECTR ODE W/CONDUCTOR. THIS MAY CAUSE A HOT ELECTRICAL SPARK.

====== Exposure Controls/Personal Protection ========

Respiratory Protection: MFR GAVE NO INFORMATION OF MSDS.

Ventilation:MFR GAVE NO INFORMATION OF MSDS.

Protective Gloves: RUBBER GLOVES.

Eye Protection: SAFETY GOGGLES OR FACE SHIELD.

Other Protective Equipment: MFR GAVE NO INFORMATION OF MSDS.

Work Hygienic Practices: AVOID SOURCES OF IGNITION WHEN CHARGING.

Supplemental Safety and Health

REFER TO MSDS FOR SULFURIC ACID.

======================================
HCC:C1 NRC/State Lic Num:NONE Appearance and Odor:GIVES OFF MIXTURE OF HYDROGEN/OXYGEN GAS WHEN ON CHARGE.
======== Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES MFR GAVE NO INFORMATION OF MSDS. Stability Condition to Avoid:MFR GAVE NO INFORMATION OF MSDS.
======= Disposal Considerations ==========
Waste Disposal Methods:DO NOT DISPOSE OF

Waste Disposal Methods:DO NOT DISPOSE OF BATTERY. SPENT OR UNUSABLE BATTERIES SHOULD BE RECYCLED BY A LICENSED BATTERY RECYCLER.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and

assume responsibility for the suitability of this information to their particular situation.