View NSN Online: https://aerobasegroup.ae/nsn/8010-01-424-8588

PFS THERMOPLASTIC POWDER COATINGS -- PF112-C102 DARK BLUE (MELT-BLENDED) 8010-01-424-8588

Product ID:PF112-C102 DARK BLUE (MELT-BLENDED) MSDS Date:10/01/1996 FSC:8010 NIIN:01-424-8588 MSDS Number: CGNNP === Responsible Party === Company Name: PFS THERMOPLASTIC POWDER COATINGS Address:3400 WEST 7TH City:BIG SPRING State:TX ZIP:79720 Country:US Info Phone Num:800 -753-5263 Emergency Phone Num:800-753-5263 OR 915263-5263 CAGE:03FB0 === Contractor Identification === Company Name: PLASTIC FLAMECOAT(R) SYSTEMS, INC. Address:3400 WEST 7TH Box:City:BIG SPRING State:TX ZIP:79720 Country:US Phone:800-753-5263 CAGE:03FB0 Ingred Name: ETHYLENE METHYLCRYLATE ACID COPOLYMER Fraction by Wt: 0-100% Other REC Limits:NONE RECOMMENDED

Ingred Name:DARK BLUE PIGMENT (SARA 313) Fraction by Wt: 0-10% Other **REC Limits:NONE RECOMMENDED**

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:INHAL: IRRITATION TO UPPER RESPIRATORY TACT. SKIN: IRRITATION, ALLERGIC REACTION. INGEST: GI IRRITATION. EYE: IRRITATION.

First Aid:INGEST: GIVE SEVERAL GLASSES OF WATER. EYE: FL USH W/WATER FOR 15 MINUTES, LIFTING LIDS. SKIN: FLUSH W/WATER FOR SEVERAL MINUTES. REMOVE & CLEAN CONTAM CLOTHES/SHOES. INHAL: GET FRESH AIR. IN ALL CASES, GET IMMED MED AID.

Flash Point:NA

====

Lower Limits:30.0 G/CM

Extinguishing Media:WATER, FOAM, CARBON DIOXIDE, DRY CHEMICAL. Fire Fighting Procedures:USE SCBA. IN CONFINED AREA USE FULL BUNKER GEAR, INCLUDE POSITIVE PRESSURE NIOSH LISTED SCBA. COOL FIRE EXP

OSED CONTAINERS W/WATER.

Unusual Fire/Explosion Hazard:DUST CAN FORM AN EXPLOSIVE MIXTURE W/AIR. ELIMINATE IGNITS.

Spill Release Procedures:REVIEW FIREFIGHTER MEASURES & HANDLING SECTIONS BEFORE PROCEEDING W/CLEANUP. USE APPROPRIATE PROTECTIVE EQUIPMENT. SWEEP UP TO AVOID SLIPPING HAZARD.

Handling and Storage Precautions: STORE IN A COOL, DRY PLAC E. KEEP

CONTAINERS CLOSED TO PREVENT CONTAMINATION & ACCUMULATION OF MOISTURE.

======= Exposure Controls/Personal Protection ===============

Respiratory Protection:USE NIOSH/MSHA APPROVED RESPIRATOR EQUIPPED W/APPROPRIATE FILTER FOR PARTICULATE DUST EXPOSURE. Ventilation:LOCAL Protective Gloves:REQUIRED Eye Protection:SAFETY GLASSES Other Protective Equipment:LONG SLEEVE COTTON SHIRT & LONG PANTS RECOMMENDED TO PREVENT SKIN CONTACT. Supplemental Safety and Health NK Melt/Freeze Pt:M.P/F.P Text:80 TO 105C Spec Gravity:>0.93 Solubility in Water:NEGLIGIBLE Appearance and Odor:FINELY DIVIDED POWDER, MILD METHACRYLIC ACID ODOR, DARK BLUE. Percent Volatiles by Volume:NONE

Stability Indicator/Materials to Avoid:YES NONE REASONABLY FORSEEABLE. Stability Condition to Avoid:TEMPS ABOVE 325C (617F). Hazardous Decomposition Product s:CARBON MONOXIDE & HYDROCARBON OXIDATION PRODUCTS INCLUDING ORGANIC ACIDS, ALDEHYDES & ALCOHOLS.

Waste Disposal Methods:PREFERRED OPTIONS. 1. RECYCLE 2. INCINERATE W/ENERGY RECOVERY. 3. LANDFILL. IN ACCORDANCE W/FEDERAL, STATE & LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United S tates of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.