

SIGMA CHEMICAL COMPANY -- T6664,TRIS BUFFERED SALINE,PH 8.0,TRU-MEASURE CHEMICAL --
6550-01-461-9032

===== Product Identification =====

Product ID:T6664,TRIS BUFFERED SALINE,PH 8.0,TRU-MEASURE CHEMICAL

MSDS Date:11/01/1998

FSC:6550

NIIN:01-461-9032

Status Code:A

MSDS Number: CKLSN

=== Responsible Party ===

Company Name:SIGMA CHEMICAL COMPANY

Box:14508

City:SAINT LOUIS

State:MO

ZIP:63178

Country:US

Info Phone Num:314-771-5765

Emergency Phone Num:314-771-5765

CAGE:TO609

=== Contractor Identification ===

Company Name:SIGMA CHEMICAL COMPANY

Box:14508

City:SAINT LOUIS

State:MO

ZIP:63178

Country:US

Phone:1-800-325-3010

CAGE:TO609

===== Composition/Information on Ingredients =====

Ingred Name:NO INGREDIENTS LISTED

===== Hazards Identification =====

LD50 LC50 Mixture:NO DATA PROVIDED BY RESPONSIBLE PARTY

Routes of Entry: Inhalation:YES Ski

n:YES Ingestion:YES

Health Hazards Acute and Chronic:ACUTE: MAY BE HARMFUL BY INHALATION, INGESTION OR SKIN ABSORPTION. CAUSES EYE AND SKIN IRRITATION. MATERIAL IS IRRITATING TO MUCOUS MEMBRANES AND UPPER RESPIRATORY TRACT.

Explanation of Carcinogenicity:NO DATA PROVIDED BY RESPONSIBLE PARTY

Effects of Overexposure:MAY BE HARMFUL BY INHALATION, INGESTION OR SKIN ABSORPTION. CAUSES EYE AND SKIN IRRITATION. MATERIAL IS IRRITATING TO MUCOUS MEMBRANES AND UPPER RESPIRATORY TRACT

Medical Cond Aggravated by Exposure:NO DATA PROVIDED BY RESPONSIBLE PARTY

=====
===== First Aid Measures =====

First Aid:EYE: IMMEDIATELY FLUSH WITH COPIOUS AMOUNTS OF WATER FOR AT LEAST 15 MINS. SKIN: IMMEDIATELY WASH WITH SOAP & COPIOUS AMOUNTS OF WATER. INHALED: REMOVE TO FRESH AIR. IF NOT BREATHING GIVE ARTIFICIAL RESPIRATION. IF BREATHING IS DIFFICULT, GIVE OXYGEN. SWALLOWED: WASH OUT MOUTH WITH WATER PROVIDED PERSON IS CONSCIOUS.

CALL A PHYSICIAN.

=====
===== Fire Fighting Measures =====

Extinguishing Media:WATER SPRAY, CARBON DIOXIDE, DRY CHEMICAL POWDER OR APPROPRIATE FOAM.

Fire Fighting Procedures:WEAR SELF CONTAINED BREATHING APPARATUS AND PROTECTIVE CLOTHING TO PREVENT CONTACT WITH SKIN AND EYES.

Unusual Fire/Explosion Hazard:EMITS TOXIC FUMES UNDER FIRE CONDITIONS.

=====
===== Accidental Release Measures =====

Spill Release Procedures:WEAR RESPIRATOR, CHEMICAL SAFETY GOGGLES,

RUBBER BOOTS & HEAVY RUBBER GLOVES. SWEEP UP, PLACE IN A BAG & HOLD FOR WASTE DISPOSAL. AVOID RAISING DUST. VENTILATE AREA & WASH SPILL SITE AFTER MATERIAL PICKUP IS COMPLETE.

Neutralizing Agent:NO DATA PROVIDED BY RESPONSIBLE PARTY

=====
===== Handling and Storage =====

Handling and Storage Precautions:CHEMICALS SAFETY GOGGLES. COMPATIBLE CHEMICAL-RESISTANT GLOVES. NIOSH/MSHA-APPROVED RESPIRATOR. SAFETY SHOWER AND EYE B

ATH. MECHANICAL EXHAUST REQUIRED.

Other Precautions:NO DATA PROVIDED BY RESPONSIBLE PARTY

=====
===== Exposure Controls/Personal Protection =====

Respiratory Protection:NIOSH/MSHA-APPROVED RESPIRATOR.

Ventilation:MECHANICAL EXHAUST REQUIRED.

Protective Gloves:COMPATIBLE CHEMICAL-RESISTANT GLOVES.

Eye Protection:CHEMICAL SAFETY GOGGLES.

Other Protective Equipment:SAFETY SHOWER, EYE BATH.

Work Hygienic Practices:NO DATA PROVIDED BY RESPONSIBLE PARTY

Supplemental Safety and Health

NO

DATA PROVIDED BY RESPONSIBLE PARTY

=====
===== Physical/Chemical Properties =====

HCC:N1

Appearance and Odor:SOLID

=====
===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

BASES, OXIDIZING AGENTS.

Stability Condition to Avoid:NO DATA PROVIDED BY RESPONSIBLE PARTY.

Hazardous Decomposition Products:THERMAL DECOMPOSITION MAY PRODUCE
CARBON MONOXIDE, CARBON DIOXIDE, AND NITROGEN OXIDES.

Conditions to Avoid Polymeriza
tion:WILL NOT OCCUR.

=====
===== Toxicological Information =====

Toxicological Information:MAY BE HARMFUL BY INHALATION, INGESTION OR
SKIN ABSORPTION. CAUSES EYE AND SKIN IRRITATION. MATERIAL IS
IRRITATING TO MUCOUS MEMBRANES AND UPPER RESPIRATORY TRACT.

=====
===== Ecological Information =====

Ecological:DATA NOT YET AVAILABLE.

=====
===== Disposal Considerations =====

Waste Disposal Methods:THE MATERIAL

SHOULD BE IGNITED IN THE PRESENCE
OF SODIUM CARBONATE & SLAKED LIME (CALCIUM HYDROXIDE). THE
SUBSTANCE SHOULD BE MIXED WITH VERMICULITE & THEN WITH THE DRY
CAUSTICS, WRAPPED IN PAPER & BURNED IN A CHEMICAL INCINERATOR
EQUIPPED WITH AN AFTERBURNER & SCRUBBER. OBSERVE ALL FEDERAL,
STATE, & LOCAL ENVIRONMENTAL REGULATIONS

===== MSDS Transport Information =====

Transport Information:NO DATA PROVIDED BY RESPONSIBLE PARTY

===== Regulatory Information =====

SARA Title III Information:NO DATA PROVIDED BY RESPONSIBLE PARTY
Federal Regulatory Information:NO DATA PROVIDED BY RESPONSIBLE PARTY
State Regulatory Information:NO DATA PROVIDED BY RESPONSIBLE PARTY

===== Other Information =====

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States of America
in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.