PRESTONE PRODUCTS CORP -- BE SERIES HEAVY DUTY REINHIBITOR 1 -- 6850-01-387-1095

Product ID:BE SERIES HEAVY DUTY REINHIBITOR 1 MSDS Date:09/22/1995 FSC:6850 NIIN:01-387-1095 Status Code:A MSDS Number: CKNHX === Responsible Party === Company Name: PRESTONE PRODUCTS CORP Address:39 OLD RIDGEBURY RD City:DANBURY State:CT ZIP:06810-5109 Country:US Info Phone Num:203-7 31-7800 Emergency Phone Num: (800) 424-9300 Resp. Party Other MSDS Num.: MSDSP145 Preparer's Name: JAMES L. OTTOWITZ Chemtrec Ind/Phone:(800)424-9300 CAGE:0CXZ7 === Contractor Identification === **Company Name: FINISH THOMPSON INC** Address:921 GREENGARDEN RD Box:City:ERIE State:PA ZIP:16501-1591 Country:US Phone:814-455-4478/800-942-5969 Contract Num:SP0450-00-M-SC42 CAGE:30255 Company Name: PRESTONE PRODUCTS CORP Address:39 OLD RIDGEBURY RD Box:City:DANBURY State:CT ZIP:06810-5109 Country:US Phone:203-7

31-3686/830-7865 CAGE:0CXZ7

======= Composition/Information on Ingredients ==============

Ingred Name:ETHYLENE GLYCOL (CONTAINS 0-8% DIETHYLENE GLYCOL) CAS#111-46-6 CAS:107-21-1 RTECS #:KW2975000 Minumum % Wt:30. Maxumum % Wt:40. ACGIH STEL:C127 MG/M3;C50 PPM EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:SODIUM MERCAPTOBENZOTHIAZOLE CAS:2492-26-4 Minumum % Wt:1. Maxumum % Wt:5.

Ingred Name:POTASSIUM HYDROXIDE CAS:1310-58-3 RTECS #:TT2100000 Minumum % Wt:7. Maxumum % Wt:13. ACGIH S TEL:C2 MG/M3 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:SODIUM SILICATE CAS:1344-09-8 Minumum % Wt:3. Maxumum % Wt:6.

Ingred Name:SODIUM TOLYLTRIAZOLE CAS:64665-57-2 Minumum % Wt:1. Maxumum % Wt:5.

Ingred Name:SODIUM BORATE CAS:1303-96-4 RTECS #:VZ2275000 Minumum % Wt:7. Maxumum % Wt:13. ACGIH TLV:5 MG/M3

Ingred Name:WATER CAS:7732-18-5 RTECS #:ZC0110000 Minumum % Wt:20. Maxumum % Wt:50.

Reports of Carcinogenic

ity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:ACUTE: SWALLOWING-INGESTION MAY RESULT IN IMMEDIATE & SEVERE BURNS TO LIPS, TONGUE, ORAL MUCOSA & ESOPHAGUS WITH POSSIBLE GASTROINTESTINAL HEMORRHAGE & PERFORATION. CARDIAC FAILURE & PULMONARY EDEMA M AY DEVELOP. SEVERE KIDNEY DAMAGE FOLLOWS SWALLOWING OF LARGE VOLUMES OF ETHYLENE GLYCOL. MAY BE FATAL. LIVER INJURY MAY OCCUR. INHALATION-EXTREME LUNG IRRITATION MAY RESULT WITH POSSIBLE DAMAGE OR DES TRUCTION OF LUNG

TISSUE RESULTING IN PNEUMONITIS OR PULMONARY EDEMA. SKIN-MAY CAUSE SEVERE SKIN IRRITATION &/OR CHEMICAL BURNS RESULTING IN TISSUE DESTRUCTION. EYE-CAN CAUSE RAPID, SEVERE IRRITATION & /OR CHEMICAL BURNS.

Explanation of Carcinogenicity:NONE OF THE INGREDIENTS IS LISTED AS A CARCINOGEN OR POTENTIAL CARCINOGEN BY IARC, NTP OR OSHA.

Effects of Overexposure:SWALLOWING-SYMPTOMS OF DROOLING, DIFFICULTY WITH SWALLOWING, BREATHING & SPEAKING, CHEST PAIN MAY BE NOTED. MAY

CAUSE ABDOMINAL DISCOMFORT OR PIAN, NAUSEA, VOMITING, DIZZINESS, MALAISE, BLURRING OF VI SION, IRRITABILITY, LUMBAR PAIN, OLIGURIA, UREMIA & CENTRAL NERVOUS SYSTEM EFFECTS, INCLUDING IRREGULAR EYE MOVEMENT, CONVULSION & COMA. A DELAYED RED SKIN RASH MAY DEVELOP. INHALATION-SYMPTOMS OF HOA RSENESS, DIFFICULT BREATHING & RESPIRATORY DISTRESS MAY BE NOTED. HIGH VAPOR CONCENTRATIONS MAY PRODUCE NAUSEA, VOMITING, HEADACHE, DIZZINESS & IRREGULAR EYE MOVEMENT.

Medical Cond

Aggravated by Exposure:MAY	AGGRAVATE EXISTING KIDNEY
DISEASE.	

First Aid:SWALLOWING-DO NOT INDUCE VOMITING. RINSE MOUTH & DRINK A GLASS OF MILK OR WATER. DO NOT GIVE ANYTHING BY MOUTH TO UNCONSCIOUS PERSON. GET IMMEDIATE MEDIAL AID. (CALL PHYSICIAN, POISION CONTROL CENTER, HOSPITAL ER) SKIN-REMOVE CONTAMINATED CLOTHING/SHOES. FLUSH SKIN WITH WATER FOR 15 MINS. IF IRRITATION, OR PAIN DEVELOPS, SEEK MED

ICAL AID. INHALATION-IF SYMPTOMPS OF EXPOSURE DEVELOP REMOVE TO FRES H AIR. IF BREATHING IS DIFFICULT, GIVE OXYGEN. PERFORM CPR IF BREATHING HAS STOPPED, & SEEK IMMEDIATE MEDICAL AID. EYES-IMMEDIATELY FLUSH WITH WATER, USING A STEADY STREAM FOR 30 MIN. SEEK MEDICAL AID.

Flash Point Method:TOC Flash Point:NO FLASH Autoignition Temp:Autoignition Temp Text:ND Lower Limits:ND Upper Limits:ND Extinguishing Media:W ATER FOG, FOAM, CARBON DIOXIDE, DRY CHEMICAL. Fire Fighting Procedures:USE POSITIVE PRESSURE SELF-CONTAINED BRATHING APPARATUS WHEN ENTERING A CONFINED SPACE. Unusual Fire/Explosion Hazard:NONE.

Spill Release Procedures:WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT FOR HANDLING CORROSIVE MATERIALS. COLLECT FOR DISPOSAL USING AN ABSORBENT MATERIAL, IE. VERMICULITE, AND PLACE IN A CONTAINER SUITABLE FOR CORROSIV E WAST E.

Handling and Storage Precautions: KEEP TIGHTLY CLOSED. DO NOT STORE IN OPEN OR UNLABELED CONTAINERS. STORE IN A COL, WELL VENTILATED AREA.. STORE AWAY FROM INCOMPATIBLE MATERIALS SUCH AS OILS, PAINTS, GASOLINE, AND FUEL PRODUCTS. KEEP AWAY FROM PAPER, RAGS, AND OTHER COMBUSTIBLES. DO NOT REUSE EMPTY CONTAINERS.

Other Precautions: FOLLOW ALL RECOMMENDED PRECAUTIONS IN HANDLING EMPTY CONTAINERS. WHEN

EMPTY, IMMEDIATELY REPACE CAP AND DISPOSE OF

PROPERLY. DO NOT CUT OR WELDON OR NEAR CONTAINER, EVEN EMPTY. EMPTY CONTANERS CONTAIN PRODUCT RESIDUES AND MAY BE DANGEROUS. HAZARDOUS REACTIONS MAY OCCUR! USE ONLY AS DIRECTED.

Respiratory Protection:NONE NEEDED UNDER NORMAL USE CONDITIONS. FOR OPERATIONS WHERE THE TLV MAY BE EXCEEDED, A NIOSH/MSHA APPROVED RESPRIRATOR WITH AN ORGANIC VAPOR CARTRIDGE & DUST/MI

ST PRE-FILTER

OR SUPPLIED AIR RESPIRAT OR IS RECOMMENDED. EQUIPMENT SELECTION DEPENDS ON CONTAMINAT TYPE/CONCENTRATION, SELECT IN ACCORDANCE WITH 29 CFR 1910.134 & GOOD INDUSTRIAL HYGIENE PRACTICE.

Ventilation:GENERAL VENTILATION ADEQUATE FOR NORMAL USE. OPERATIONS WHERE THE MATERIAL IS HEATED, MISTED, TLV EXCEEDED, FORCED VENTILATION (LOCAL EXHAUST) MAYBE NEEDED.

Protective Gloves: CHEMICAL RESISTANT (NEOPRENE OR PVC COATED) GLOVES. Eye Protection: SPLASH-PROOF CHEMICAL SAFE TY GOGGLES.

Other Protective Equipment:PROTECTIVE CLOTHING SUCH AS APRON, COVERALL, AND BOOTS IF NEEDED TO PREVENT SKIN CONTACT. SUITABLE WASHING AND EYE FLUSHING FACILITIES SHOULD BE AVAILABLE IN THE IMMEDIATE WORK AREA.

Work Hygienic Practices: CONTAMINATED CLOTHING SHOULD BE IMMEDIATELY REMOVED AND LAUNDERED BEFORE RE-USE. PREVENT CONTACT WITH EYES, SKIN & CLOTHING. IMMEDIATELY REMOVE CONTAMINATED CLOTHING & LAUNDER BEFORE RESUE.

Supplemental Safety and Health

SPECIAL P

RECAUTIONS: CORROSIVE! DO NOT BREATHE VAPOR OR MIST THAT MAY GENERATE IN USING THE CHEMICALS. USE ONLY WITH PROPER VENTILATION. WASH EXPOSED SKIN THOROUGHLY WITH SOAP & WATER AFTER USE. DO NO T MIX THIS CHEMICAL DIRECTLY WITH OTHER MATERIAL. RESPIRATORY: FOR FIREFIGHTING USE SELF-CONTAINED BREATHING APPARATUS.

HCC:B1 Boiling Pt:>104.4C, 220.F Melt/Freeze Pt: