View NSN Online: https://aerobasegroup.ae/nsn/5970-00-935-4941

DEXTER CORP THE DEXTER ELECTRONIC MATERIAL DIV. -- PO0011, HYSOL PC18M

5970-00-935-4941

============= Product Identification =================

Product ID:PO0011, HYSOL PC18M

MSDS Date:04/14/2000

FSC:5970

NIIN:00-935-4941 Status Code:A

MSDS Number: CKWJJ === Responsible Party ===

Company Name: DEXTER CORP THE DEXTER ELECTRONIC MATERIAL DIV.

Address:211 FRANKLIN ST.

City:OLEAN State:NY

ZIP:14760-1297 Country:US

Info

Phone Num:716-372-6300/6309

Emergency Phone Num:800-424-9300 Chemtrec Ind/Phone:(800)424-9300

CAGE:04347

=== Contractor Identification ===

Company Name: DEXTER CORP THE DEXTER ELECTRONIC MATERIAL DIV

Address:211 FRANKLIN ST.

Box:City:OLEAN

State:NY

ZIP:14760-1297

Country:US

Phone:716-372-6300/6309

CAGE:04347

Company Name: MCKEOWN ROBERT CO. INC.

Address:111 CHAMBERS BROOK RD.

Box:City:SOMERVILLE

State:NJ ZIP:08876 Country:US

Phone:908-218-9000

Contract Num:SP0450-01-M-H373

CAGE:7B953

= Composition/Information on Ingredients ========== Ingred Name: 2-PROPANOL, 1-METHOXY-, ACETATE CAS:108-65-6 RTECS #:AI8925000 Minumum % Wt:10. Maxumum % Wt:30. OSHA PEL:N/D ACGIH TLV:N/D Ingred Name:XYLENE CAS:1330-20-7 RTECS #:ZE2100000 Minumum % Wt:10. Maxumum % Wt:30. OSHA PEL:435 MG/M3 ACGIH TLV:434 MG/M3;100 PPM ACGIH STEL:651 MG/M3;150 PPM EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS Ingred Name:BENZENE, ETHYL-CAS:100-41-4 RTECS #:DA0700000 Minumum % Wt:1. Maxumum % Wt:5. **OSHA PEL:4** 35 MG/M3;100 PPM ACGIH TLV:434 MG/M3;100 PPM ACGIH STEL:543 MG/M3;125 PPM EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS Ingred Name:TOLUENE CAS:108-88-3 RTECS #:XS5250000 = Wt:.2OSHA PEL:754 MG/M3 ACGIH TLV:188 MG/M3;50 PPM EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS Ingred Name:BENZENE, 1,3-DIISOCYANATOMETHYL-CAS:26471-62-5 RTECS #:NQ9490000 = Wt:1.OSHA PEL:N/D ACGIH TLV:N/D

EPA Rpt Qty:100 LBS DOT Rpt Qty:100 LBS

========= Hazards Identification =============

LD50 LC50 M

ixture:NO DATA PROVIDED BY MANUFACTURER

Reports of Carcinogenicity:NTP:YES IARC:YES

Health Hazards Acute and Chronic:TARGET ORGANS: EYES, SKIN, RESPIRATORY TRACT. EYE: CONTACT MAY CAUSE EYE IRRITATION. SKIN: PROLONGED OR REPEATED SKIN CONTACT MAY CAUSE IRRITATION. CONTACT WITH PRODUCT AT ELEVATED TEMPERATURES (>150 1/2C) CAN RESULT IN THERMAL BURNS. INHALATION: HARMFUL IF INHALED, MAY CAUSE ALLERGIC RESPIRATORY REACTION SUCH AS ASTHMA. INGESTION: MODERATELY TOXIC, MAY CAUSE

VOMITING.

Explanation of Carcinogenicity:BENZENE IS LISTED AS GROUP 2B (IARC), GROUP 2 (NTP).

Effects of Overexposure:EYE: IRRITATION. SKIN: IRRITATION. CONTACT WITH PRODUCT AT ELEVATED TEMPERATURES (>150 1/2C) CAN RESULT IN THERMAL BURNS. INHALATION: ALLERGIC RESPIRATORY REACTION SUCH AS ASTHMA. INGESTION: VOMITING.

Medical Cond Aggravated by Exposure:PREEXISTING SKIN AND EYE DISORDERS
MAY BE AGGRAVATED BY EXPOSURE TO THIS PRODUCT. PREEXISTING SKIN AND
LUNG ALLER

GIES MAY INCREASE THE CHANCE OF DEVELOPING INCREASED ALLERGIC SYMPTOMS FROM EXPOSURE

	Time 4 Airl Management	
=======================================	First Aid Measures	

First Aid:EYE: IMMEDIATELY WASH/FLUSH EYES WITH WATER FOR MINIMUM 10 MINUTES. SEEK MEDICAL ATTENTION. SKIN: WASH OFF IN FLOWING WATER OR SHOWER. REMOVE CONTAMINATED CLOTHING AND SHOES. SEEK MEDICAL ATTENTION, I F IRRITATION DEVELOPS. INHALTION: MOVE TO FRESH AIR. IF NOT BREATHING, GIVE MOUTH TO MOUTH RESUSCITATION. IF BREATHING

IS DIFFICULT, GIVE OXYGEN. SEEK MEDICAL ATTENTION. INGESTION: IF SWALLOWED, DO NO T INDUCE VOMITING. SEEK PROMPT MEDICAL ATTENTION. NOTE TO PHYSICIAN: TREATMENT SHOULD BE DIRECTED AT THE CONTROL OF SYMPTOMS AND THE CLINICAL CONDITIONS. ANTIDOTES: THERE ARE NO SPECIFIC ANTIDOTES.

Flash Point Method:CC
Flash Point:=31.7C, 89.F
Extinguishing Media:WATER FOG, CARBON DIOXIDE, DRY CHEMICAL, FOAM.
Fire Figh

ting Procedures:RECOMMEND USE OF SELF CONTAINED BREATHING APPARATUS (SCBA).
Unusual Fire/Explosion Hazard:NO UNUSUAL FIRE OR EXPOSION HAZARDS.
========= Accidental Release Measures ==========
Spill Release Procedures:CONTAIN SPILL IN NATURAL FORM OR WITH SAND AND DIRT(INERT MATERIAL). ELIMINATE ALL IGNITION SOURCES. PREVENT RUNOFF TO STORM SEWERS, DITCHES AND WATERWAYS. SHOVEL OR SCRAPE(NON-METALLIC) ABSORBED WAST E MATERIAL INTO DISPOSAL CONTAINER. SEAL LID TIGHTLY WITH TAPE OR LOCKING RING AND LABEL PROPERLY. CLEAN UP SPILL, OBSERVING PRECAUTIONS INCLUDING ADEQUATE VENTILATION AND/OR PROTECTIVE EQUIPMENT.
Neutralizing Agent:NO DATA PROVIDED BY MANUFACTURER
======================================
Handling and Storage Precautions:PLASTIC CONTAINERS MAY BE SLIPPERY WHEN HANDLING. STORAGE: LESS THAN 25 DEGREES C (