

FLEX-O-LITE INC -- GLASS BEADS, BLAST-O-LITE -- 5350-00-012-1869

=====  
Product Identification  
=====

Product ID:GLASS BEADS, BLAST-O-LITE  
MSDS Date:07/15/2001  
FSC:5350  
NIIN:00-012-1869  
Status Code:A  
MSDS Number: CLHPZ  
=== Responsible Party ===  
Company Name:FLEX-O-LITE INC  
Address:125 CASSENS COURT  
City:FENTON  
State:MO  
ZIP:63026  
Country:US  
Info Phone Num:636 349-1193 EMER: 800-535-5053  
Emergency Ph  
one Num:800-535-5053  
CAGE:UO651  
=== Contractor Identification ===  
Company Name:FLEX-O-LITE INC  
Address:125 CASSENS COURT  
Box:City:FENTON  
State:MO  
ZIP:63026  
Country:US  
Phone:636 349-1193 EMER: 800-535-5053  
CAGE:UO651

=====  
Composition/Information on Ingredients  
=====

Ingred Name:GLASS BEADS (ALL COMPONENTS ARE AMORPHOUS AND  
NON-CRYSTALLINE)  
> Wt:99.  
OSHA PEL:R DUST 5 MG/M3  
ACGIH TLV:T DUST 10 MG/M3

=====  
Hazards Identification  
=====

R

outes of Entry: Inhalation:YES Skin:NO Ingestion:NO

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:INHALATION: (ACUTE & CHRONIC):

REPEATED OR PROLONGED INHALATION OF DUST IN EXCESS OF PERMISSIBLE EXPOSURE LIMITS MAY RESULT IN IRRITATION TO THE RESPIRATORY TRACT. CHRONIC RESPIRATORY CONDITIONS MAY BE AGGRAVATED BY EXPOSURE TO HIGH CONCENTRATIONS OF DUST.

Explanation of Carcinogenicity:NOT LISTED BY OSHA, NTP OR IARC

Effects of Overexposure:

IRRITATION OF EYES AND RESPIRATORY TRACT.

Medical Cond Aggravated by Exposure: CHRONIC RESPIRATORY CONDITIONS MAY BE AGGRAVATED BY EXPOSURE TO HIGH CONCENTRATIONS OF DUST.

=====  
===== First Aid Measures =====

First Aid:EYE EXPOSURE: FLUSH WITH COPIOUS AMOUNTS OF WATER.  
INHALATION: MOVE TO FRESH AIR.

=====  
===== Accidental Release Measures =====

Spill Release Procedures:AVOID EXCESS DUSTING. SWEEP OR VACUUM SPILLED MATERIAL.

=  
=====  
===== Handling and Storage =====

Handling and Storage Precautions:AVOID EXCESSIVE DUSTING.

=====  
===== Exposure Controls/Personal Protection =====

Respiratory Protection:NIOSH/OSHA APPROVED DUST MASK IF PERMISSIBLE EXPOSURE LEVELS ARE EXCEEDED.

Eye Protection:SAFETY GLASSES OR GOGGLES ARE RECOMMENDED.

Supplemental Safety and Health

=====  
===== Physical/Chemical Properties =====

HCC:N1

Spec Gravity:2.5

Solubility in Wate

r:INSOLUBLE

Appearance and Odor:WHTe /OFF-WHITE POWDER / GRANULAR MATERIAL.  
ODORLESS.

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

HYDROFLUORIC, FLUOROSILICIC AND PHOSPHORIC ACIDS AND HOT STRONG  
ALKALINE SOLUTIONS.

Stability Condition to Avoid:STABLE

===== Disposal Considerations =====

Waste Disposal Methods:MAY BE DISPOSED OF IN APPROVED LANDFILL IN  
ACCORDANCE WITH FEDERAL, STATE AN  
D LOCAL REGULATIONS.

===== Other Information =====

Disclaimer (provided with this information by the compiling agencies):  
This information is formulated for use by elements of the Department  
of Defense. The United States of America in no manner whatsoever,  
expressly or implied, warrants this information to be accurate and  
disclaims all liability for its use. Any person utilizing this  
document should seek competent professional advice to verify and  
assume responsibility for the suitability of this information to their  
particular situation.