

LOCTITE CORPORATION -- FAST CURE EPOXY - RESIN

=====  
MSDS Safety Information  
=====

FSC: 8040  
NIIN: 01-046-5061  
MSDS Date: 05/12/1999  
MSDS Num: CLJMS  
Product ID: FAST CURE EPOXY - RESIN  
MFN: 01  
Responsible Party  
Cage: 05972  
Name: LOCTITE CORPORATION  
Address: 1001 TROUT BROOK CROSSING  
City: ROCKY HILL  
CT 06067-3910  
Info Phone Number: 860-571-5100  
Emergency Phone Number: 860-571-5100  
Preparer's Name: HENRY SIMMONS  
Review Ind: Y  
Published: Y

=====  
Contractor Summary  
=====

Cage: 05972  
Name: LOCTITE CORPORATION  
Address: 1001 TROUT BROOK CROSSING  
City: ROCKY HILL CT 06067-3910  
Phone: 860-571-5100

=====  
Item Description Information  
=====

Item Manager: GSA  
Item Name: ADHESIVE  
Unit of Issue: KT  
UI Container Qty: 0

=====  
Ingredients  
=====

Name: EPOXY RESIN  
% low Wt: 45.  
% high Wt: 50.

-----  
Cas: 21645-51-2  
RTECS #: BD0940000  
Name: ALUMINUM HYDROXIDE  
% low Wt: 45.  
% high Wt: 50.  
OSHA PEL: 15 MG/M3  
ACGIH TLV: 10 MG/M3

-----  
Cas: 13463-67-7  
RTECS #:

XR2275000

Name: TITANIUM DIOXIDE

% low Wt: 5.

% high Wt: 10.

OSHA PEL: 15 MG/M3

ACGIH TLV: 10 MG/M3

ACGIH STEL: NOT ESTABLISHED

-----  
Cas: 112945-52-5

RTECS #: VV7310000

Name: SILICA, AMORPHOUS, FUMED, CRYST.-FREE

% low Wt: 1.

% high Wt: 3.

Other REC Limits: 3 MG/M3

OSHA PEL: 6 MG/M3

ACGIH TLV: 10 MG/M3

=====  
Health Hazards Data

=====  
Route Of Entry Inds - Inhalation: YE

S

Skin: YES

Ingestion: YES

Effects of Exposure: EYE AND SKIN IRRITANT. REPEATED OR PROLONGED EXPOSURE BY INGESTION MAY CAUSE WE DELAYED EFFECTS INVOLVING THE BLOOD, GASTROINTESTINAL, NERVOUS, AND REPRODUCTIVE SYSTEMS. MAY BE A POTENTIAL HUMAN SKIN CARCINOGEN.

Signs And Symptoms Of Overexposure: MAY CAUSE DERMATITIS ON PROLONGED CONTACT IN SENSITIVE INDIVIDUALS.

Medical Cond Aggravated By Exposure: NONE KNOWN

First Aid: INGESTION: INDUCE VOMITING. OBTAIN MEDICAL ATTENTION. INHALATION:

REMOVE TO FRESH AIR. IF SYMPTOMS PERSIST, OBTAIN MEDICAL ATTENTION. SKIN CONTACT: FLUSH WITH WATER. EYE CONTACT: FLUSH AT LEAST 15 MINUTES WITH WATER. OBTAIN MEDICAL ATTENTION.

=====  
Handling and Disposal

=====  
Spill Release Procedures: SOAK UP IN AN INERT ABSORBENT. STORE IN A PARTLY FILLED CLOSED CONTAINER UNTIL DISPOSAL.

Waste Disposal Methods: INCINERATE FOLLOWING EPA AND LOCAL REGULA

CTIONS

Handling And Storage Precautions: SAFE STORAGE: STORE BELOW 100F (CONTACT  
LOCTITE CUSTOMER SERVICE 1-800-243-4874 FOR SHELF LIFE INFORMATION)  
HANDLING: KEEP AWAY FROM EYES. AVOID PROLONGED SKIN CONTACT.

=====  
Fire and Explosion Hazard Information  
=====

Flash Point Method: TCC  
Flash Point: >93.3C, 200.F  
Lower Limits: 3.2%  
Upper Limits: 15.3%  
Extinguishing Media: CARBON DIOXIDE, FO  
AM, DRY CHEMICAL  
Unusual Fire/Explosion Hazard: IRRITATING ORGANIC VAPOR.

=====  
Control Measures  
=====

Ventilation: SUFFICIENT TO MAINTAIN VAPOR CONCENTRATION BELOW TLV.  
Protective Gloves: RUBBER OR PLASTIC GLOVES RECOMMENDED  
Eye Protection: SAFETY GLASSES OR GOGGLES RECOMMENDED.

=====  
Physical/Chemical Properties  
=====

Boiling Point: >148.9C, 300.F  
Vapor Pres: < 5 MM AT 80 F  
Spec Gravity: 1.68  
VOC Grams/Liter: 8  
Solubility in Water: SLIGHT  
Appearance and Odor: WHITE PASTE AND MILD ODOR

=====  
Reactivity Data  
=====

Stability Indicator: YES  
Materials To Avoid: NONE  
Hazardous Polymerization Indicator: NO

=====  
Regulatory Information  
=

=====  
State Regulatory Information: WARNING: THIS PRODUCT CONTAINS A CHEMICAL KNOWN  
TO THE STATE OF CALIFORNIA TO CAUSE CANCER. EPHICHLOROHYDRIN.  
=====

HAZCOM Label  
=====

Product ID: FAST CURE EPOXY - RESIN  
Cage: 05972  
Company Name: LOCTITE CORPORATION  
Street: 1001 TROUT BROOK CROSSING  
City: ROCKY HILL CT  
Zipcode: 06067-3910  
Health Emergency Phon

e: 860-571-5100

Label Required IND: Y

Date Of Label Review: 08/17/2001

Status Code: A

Origination Code: G

Hazard And Precautions: EYE AND SKIN IRRITANT. REPEATED OR PROLONGED EXPOSURE BY INGESTION MAY CAUSE WE DELAYED EFFECTS INVOLVING THE BLOOD, GASTROINTESTINAL, NERVOUS, AND REPRODUCTIVE SYSTEMS. MAY BE A POTENTIAL HUMAN SKIN CARCINOGEN.

=====  
Disclaimer (provided with this information by the compiling agencies): This information is for

mulated for use by elements of the Department of Defense.

The United States of America in no manner whatsoever expressly or implied warrants, states, or intends said information to have any application, use or viability by or to any person or persons outside the Department of Defense nor any person or persons contracting with any instrumentality of the United States of America and disclaims all liability for such use. Any person utilizing this instruction who is not a military or civ

ilian employee of the

United States of America should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation regardless of similarity to a corresponding Department of Defense or other government situation.