## NSN 1620-01-125-6999

Repairability:

Tail Bumper Yoke Assembly - Page 1 of 1



/iew Online at https://aeroba	segroup.ae/nsn/1620-01-125-	6999		
Shelf Life:				
N/a				
Jnit Of Measure:				
ea				
Demilitarization:				
es - demil/mli				
lazmat:				
No				

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.