NSN 2915-01-336-5167

Repairability:

Turbine Engine Main Fuel Control - Page 1 of 1



When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.