NSN 5985-01-511-2032

Radio Frequency Transmission Line Switch - Page 1 of 1



Repairability:

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.